

(08/1/13) Wel

ASS. REC. BY:

REF: CS/SMR24100489/Rvp3

930A

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SGA 3818R

Yr Regn:

2015, Jan

Type: ☒ Car / ☐ Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

OD ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SGA 3818R

Make: HONDA HCU 1.5 LX CVT CC 1497

at Workshop m/o WAH HONK

Colour: GREY AC: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

of 42, TOH GUAN RD EAST

Sp. Reading: 293263 TRadio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Insured: SG 5827L SMR

Eng No:

Policy No.

CNo: MR HCU 1830 FP 000153

Claims No. BUS/10/24/7021

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / ☐ Jammed / ☐ Locked / ☐ Burnt or

(Client's Record)

Brake: ☒ Inorder / ☐ Jammed / ☐ Locked / ☐ Burnt or

Make of Veh:

Mod: ☐ Nil / ☐ STD / ☐ STD A/R or

(Policy Condition)

10am

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

225/50R17

Bal. or Market Value:

20K

Front

Rear

IDAC Accident Report:

Consistent?: Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Scan:

Consistent?: Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

11/10/24

D.O.I.

12/11/24

Lum Sum:

%

3 Val.: Yes or No

Survey held at

TOH GUAN

CA / REV / REP. / 24 HRS

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

REAR O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LMT - 7K

19/11/24 Rasul confirmed final fig \$3624.47 (red 4744.13, 56%)

Date/Time, File Path



Prel. Report

Days Of Repair: 5

Date/Time, File Path

Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation

2)

Add Fee:

Site Insp (\$

Interview (\$

Tech. Insp (\$

Weekend (\$

S + R

Photos

Others

Report Format:

Lump Sum / I.B.I. (\$



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: UC1400
Vehicle No.	: SGQ3818R
Make & Model	: HONDA HRV 1.5 LX CVT

UEN IN

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear windscreen moulding <i>acc</i>		160.00	
1	Tail lamp RH <i>cm</i>		525.00	
1	Boot lid lamp RH <i>cm</i>		295.00	
1	Boot lid <i>bt</i>		1050.00	
1	Boot lid top garnish <i>cm</i>		190.00	
1	Boot lid logo badge <i>acc</i>		16.00	
1	Boot lid emblem "HR-V" <i>acc</i>		17.00	
1	Boot lid emblem "I-VTEC" <i>acc</i>		18.00	
2	Boot lid hinge RH/LH@2*\$45 <i>X</i>		90.00	
1	Boot lid weatherstrip <i>de</i>		108.00	
1	Boot lid stopper RH <i>acc</i>		11.00	
1	Boot lid cover RH <i>X</i>		14.00	
1	Boot lid trim board <i>?</i>		149.00	
1	Boot lid trim board handle <i>X</i>		19.00	
1	Rear side bumper RH <i>cut</i>		94.00	
1	Rear side bumper retainer RH <i>?</i>		19.00	
1	Rear bumper <i>de</i>		3464.00	
1	Rear bumper stopper RH <i>cm</i>		13.00	
1	Rear reflector RH <i>?</i>		190.00	
1	End panel top garnish <i>?</i>		67.00	
1	End panel <i>?</i>		408.00	
1	Rear fender RH (repair refer to labour)		0.00	
			6917.00	
Part Items Total:			-20%	
			-1383.40	
			5533.60	
SPECIAL NETT ITEMS				
1	Rear windscreen sealant <i>acc</i>		60.00	<i>to</i>
1	End panel sealant <i>?</i>		60.00	<i>to?</i>
1	Rear carplate with holder <i>X</i>		35.00	
SN Items Total:			155.00	
Total Parts:			5688.60	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: UC1400
Vehicle No.	: SGQ3818R
Make & Model	: HONDA HRV 1.5 LX CVT

Page No. 1

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	600.500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	400.300
3	To perform anti-rust treatment on affected areas	90.00	40
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	40
5	To remove and refit rear seat compartment fitting, trimmings, garnish and etc	100.00	50?
6	To carried out repair and refit/replace of rear windscreen	100.00	
7	To remove and replace rear parking sensor	100.00	50
Labour Total :		2680.00	
TOTAL (PARTS & LABOUR):		8368.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Res
Hp 900 00068
5 days
P/P
12/11/24
Res after repair



Honda HR-V 1.5A LX

\$29,800 Instalment \$1,781/mth

PREMIUM AD

♡ Shortlist

✓ Get Warranty

📅 Loan Calculator

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

▶ **VIEW ALL
PROMO**

Overview Financial Photo Research

Depreciation	ⓘ \$16,220 / year
Reg. Date	15-Dec-2015 (1yr 1mth 2days COE left)
Manufactured	ⓘ 2015
Mileage	109,000 km (12.2k / year)
Transmission	Auto
Engine Cap	1,497 cc
Road Tax	ⓘ \$684 / year
Power	88.0 kW (118 bhp) View specs of the Honda HR-V (2015-2021)
Curb Weight	ⓘ 1,221 kg
COE	ⓘ \$56,001
OMV	ⓘ \$23,082
ARF	ⓘ \$24,315
Dereg Value	ⓘ \$19,464 as of today
No. of Owners	ⓘ 1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	930A
Vehicle Details	
Vehicle No.:	SGQ3818R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2024
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15Z71000182
Chassis No.:	MRHRU1830FP000153
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$21,608.00
Original Registration Date:	19 Jun 2015
First Registration Date:	19 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$17,252.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2025
PARF Rebate Amount:	\$8,626.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,589.00
COE Rebate Amount:	\$4,115.00
Total Rebate Amount:	\$12,741.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 12 Nov 2024

OK