

Name & Address:

Motor Claims Department

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Email/Fax No:

Contact No:

Vehicle No:

SNK3395S

Brand & Model:

BMW 118i

Chassis/VIN No:

WBA7K320705R76557

WIP#:

29554

Date:

25-Oct-24

Franchise:

BMW

Contact Person (Eurokars):

HUI WEN

Contact No (Eurokars):

6331 0680

Type of Claim:

THIRD PARTY

YEAR MODEL:

29/10/2020

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER	51 12 9881580	1		-	\$ Rp 1,132.45
2	LOWER BUMPER TRIM	51 12 8070950	1		-	\$ del 269.65
3	CLAMP	07 14 7332700	6		-	\$ X m 20.10
4	EXPANDING RIVET	07 14 7148444	6		-	\$ net 16.50
5	TOWING COVER	51 12 9881582	1		-	\$ X 56.50
6	KIT, MOUNT PDC	51 12 9881581	1		-	\$ X 75.55
7	CORNER BUMPER MOUNT LH	51 12 7461397	1		-	\$ X 53.70
8	CORNER BUMPER MOUNT RH	51 12 7461398	1		-	\$ X 53.70
9	GUIDE, CENTER	51 12 8496655	1		-	\$ X 172.60
10	MOUNT FOR SMO	51 12 8072572	1		-	\$ X 123.85
11	PLUG-IN NUT	51 12 7461407	6		-	\$ net 19.20
12	REAR REINFORCEMENT	51 12 7462338	1		-	\$ X m 477.95
13	WASHER-GASKET	51 12 7300789	2		-	\$ X m 23.80
14						\$ -

Sub-Total (Parts Price) \$ **305,35** - \$ 2,495.55

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER , REAR REINFORCEMETN AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	850.	\$ 1,700.00
2	TO RESPRAY REAR BUMPER.	1000	\$ 1,500.00
3	TO TRANSFER THE REVERSE SENSORS.	150. nett	\$ 500.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ ✓ 500.00
6	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time:

Repair Days:

Excess:

Sub-Total (Labour Price) \$

- \$ 4,500.00

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

	REVISED	PRICE
Parts Price	\$ -	\$ 2,495.55
Labour Price	\$ -	\$ 4,500.00
Total (Initial Estimate)	\$ -	\$ 6,995.55
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 6,995.55
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 6,995.55
GST 9%	\$ -	\$ 629.60
GRAND TOTAL	\$ -	\$ 7,625.15

Taufik 9749549 / 62563561
 WP 30/10/2010
 3 days
 Resurvey new parts with old part
 tafik@clhamp.com

305.55
 2670
 2975.35
 3 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: