



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24100494/Rqh3m4(N) Date: 03/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 9997J	Veh. Inspected	SMM 9874M
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS24/3335	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	28/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESQUIRE HYBRID 1.8GI	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	ZWR800391574	Colour	GREY
	Odometer	156850 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/50 ZR17	ARDENT	6 mm
	L/H Front Tyre	215/50 ZR17	ARDENT	6 mm
	R/H Rear Tyre	215/50 ZR17	ARDENT	6 mm
	L/H Rear Tyre	215/50 ZR17	ARDENT	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2024	Inspection Date	29/10/2024
	Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723		
5a. Remarks				
	A)REGISTRATION DATE: 22 JUL 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	