

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133/ 62717433 FAX: 62745715

Pg 1

DOA: 27.10.2024

No	Description	Unit	List (\$)
1	REAR TAILGATE bt ✓	1	\$ 1812.70 1,909.70
2	REAR TAILGATE ABSOBER X	2	\$ X 597.20
3	REAR TAILGATE GLASS MOUNDING m ✓	SET	\$ 185.20 195.00
4	REAR TAILMGATE EMBLEM "ESQUIRE" m ✓	1	\$ 93.20 100.00
5	REAR TAILGATE LOCK 9.b ✓	1	\$ 581.90 715.88
6	REAR TAILGATE TRIM BOARD ? X	1	\$ X 720.85
7	REAR TAILGATE WEATHERSHIP ? X	1	\$ X 360.50
8	REAR BUMPER de ✓	1	\$ / 920.90
9	REAR BUMPER SIDE RETAINER *Short ? X	1 ✓	\$ X 230.00
10	REAR BUMPER SIDE RETAINER * Long ? X	1 ✓	\$ X 270.00
11	REAR BUMPER REFLECTOR (RH) ?X/LH-X	1 ✓	\$ X 190.00
12	REAR END PANEL ? Repair	1	\$ XR 770.50
13	REAR END PANEL GARNISH de ✓	1	\$ 148.60 340.40
14	REAR SPRAE TYRE PANEL X	1	\$ X 800.90
15	REAR SPARE TYRE CARMAT X	1	\$ X 495.00
16	REAR BUMPER SENSOR ? X	2	\$ X 580.00
17	REAR BUMPER SENSOR HOUSING m ✓	2	\$ / 130.00
18	REAR SENSOR ANTENNA ? X	1	\$ X 285.75
19	REAR BUMPER CENTER BRACKET ? X	1	\$ X 320.00
			3872.50
			259.
			2904.37
			/
		Total (A) :	\$ 9,932.58
		Less 25%	\$ 2,483.15
		Total:	\$ 7,449.44

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg 2

Liberty Insurance Pte Ltd

Date: 28.10.2024

Owner's Name : Jacquelyn Goh

Vehicle No : SMM9874M

Claim Type: Third Party Claim

Vehicle Make & Model : Toyota Esquire Hybrid 1.8 GI CVT

Chassis No: ZWR800391574

Registration Date : 22 Jul 2019 (YOM 2019) COE Expiry Date 21 Jul 2029

DOA: 27.10.2024

[illegible]

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133 62717433 FAX: 62745715

Pg 3

DOA: 27.10.2024

[illegible]