

REF:

CS/AIG24100507/Anp3 (SND 1510B)

ASSIGNMENT

Front: _____ Date: _____

Estn: _____

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle NO: _____at W/O m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: 800

(Client's Record)

Make of Vcl: _____

(Policy Condition)

N/S	O/S

Remark: Therah had commenced its repair at the time of inspection.

Bal. or Mater Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SND1510B Yr Regn: 2021 DecType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi Q3 C.O. 1395Colour: White A/C: Insured / Std / NI / NASp. Reading: 50313 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF36M1156897Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/65R17R: 215/65R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 26 mmR/Bal. 26 mmL/Bal. 96 mmL/Bal. 96 mm

D.O.A. _____

D.O.A. 30/10/24

Survey held at

PremiumDes. of Damages: Fnt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 AIG

COE Expiry: _____

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 152KPV: 802KNett: 71.8K

We will be advising our principal a cost of repair of \$6,008.48 before excess \$800 & GST with 4 days (red, \$23181.52, 79%)

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 4

1)



Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS: \$1 _____

Photos _____

Others _____

Report Format: _____

Report Form / L.P. / C

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0824/2024/KS
DATE : 29-Oct-24
WIP : 36420

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS MOHANA KUMAR KRITHIKA
ADDRESS : BLK 75 PASIR RIS GROVE
#10-30
SINGAPORE 518207
TELEPHONE : HP +65 83281236
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210148155-01
VEHICLE NO : **SND 1510 B**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 9/12/2021
ENGINE NO : CZD C50056
CHASSIS NO : WAUZZZF36M11156897
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Oct-24
PLACE OF ACCIDENT : NEAR PASIR RIS MULTI STOREY CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SND 1510 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	✓
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHEN NECESSARY.	S/N \$ 1,800.00	X
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIR BAG ETC.	S/N \$ 1,800.00	X
5	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	500
6	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, ROOF CHANNEL, LHS SILL PANEL, REAR END PANELLING, DOOR ENTRANCE DRAIN CHANNEL AND LHS REAR DOOR HANDLE.	\$ 5,500.00	1200
7	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	\$ 500.00	X
8	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	\$ 400.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	\$ 292.00	✓
TOTAL LABOUR CHARGES		\$ 17,452.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1530 U.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Dented</i>	1	\$ 3,329.00	✓
2	REAR DOOR OUTER SEAL - LH <i>for</i>	1	\$ 168.00	✓
3	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 342.00	+
4	REAR DOOR CATCH - LH <i>?</i>	1	\$ 150.00	?
5	REAR DOOR HANDLE, EXTERIOR - LH <i>cut</i>	1	\$ 240.00	✓
6	REAR DOOR HANDLE UNDERLAY - LH REAR <i>new</i>	1	\$ 7.00	+
7	REAR DOOR HANDLE MOUNTING BAR <i>new</i>	1	\$ 186.00	+
8	REAR DOOR COVER - LH REAR <i>cut</i>	1	\$ 304.00	✓
9	REAR FENDER - LH <i>Repair</i>	1	\$ 4,200.00	+
10	REAR QUARTER GLASS - LH <i>new</i>	1	\$ 769.00	+
11	PRIMER <i>new</i>	1	\$ 27.00	+
12	REAR WHEEL ARCH COVER - LH / RH <i>LH cut</i>	2	\$ 636.00	318
13	1/4 GLASS SEALANT	S/N	\$ 100.00	+
14	METAL FILLER POWDER	S/N	\$ 280.00	+
15	ACRYLIC SEALANT	S/N	\$ 180.00	+
16	STONE CHIP	S/N	\$ 180.00	+
17	CAVITY WAX	S/N	\$ 140.00	+
18	SUNDRIES <i>?</i>		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 11,738.00	
TOTAL LABOUR CHARGES		:	\$ 17,452.00	
GRAND TOTAL		:	\$ 29,190.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *30/10/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT