Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way #09-16

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 Singapore 079120

Attn: Wan, Haohui Date: 01 Nov 2024

Preliminary Advice

Vehicle No : SND1510B Accident Date : 25/10/2024 Make : AUDI Q3 Policy No. : 7210148155-01 **Assignment Date** : 29/10/2024 Excess : S\$800.00

Date of Inspection : 30/10/2024 Est. Duration of Repair : 4

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,190.00
Revised Amount	:S\$	6,751.00
Check Items (Estimated)	:S\$	650.00
Total	:S\$	7,401.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 152,000.00 COE / PARF Rebate :S\$ 80,112.00

Salvage Value :S\$

Margin for Repair :S\$ 71,888.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kin-	dly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.