



ESTIMATE

Account Details		Account No.		Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11 Document No. 0 Document Date 26/10/2024		Mr Tan Chee Keong (Chen Zhiqiang) 10 Lorong Ampas #15-05 Singapore 328784 Mobile: 80878807				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2024	MXPL10R	MWXUB E1	26/04/2024	SNS4448A	0	34203	79/DS/SNS4448A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDBBBA320L001625		M15AY955689	60	Ong Wen Hong				
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:CHINA TAIPING TP VEH:SMM418G DATE OF ACC:25/10/2024 NUMBER OF REPAIR DAYS: SURVEY BY:						50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)						100.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS						1584 3168.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS						1312 2824.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM						134.64
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR						MX 198.00
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT						594.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						198.00
9	B	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN						594.00
10	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN						480.00
11	1	T52159-5C916 COVER, RR BUMPER			1.00	516.40		516.40
12	2	S52161-0K040 PIECE, RR BUMPER			8.00	5.80		46.40
13	3	T89348-52250 B0 RETAINER, ULTRASONIC			2.00	55.10		110.20
14	4	T89348-33270 P0 RETAINER, ULTRASONIC			2.00	55.20		110.40
								(55.20) 110.40
								X 2
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		



Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 NO 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #15-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICC11		Mr Tan Chee Keong (Chen Zhiqiang)		
				Document No. 0		10 Lorong Ampas #15-05 Singapore 328784		
				Document Date 26/10/2024		Mobile: 80878807		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2024	MXPL10R	MWXUB E1	26/04/2024	SNS4448A	0	34203	79/DS/SNS4448A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDBBBA320L001625		M15AY955689	60	Ong Wen Hong				
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	5	RETAINER, RR BUMPER <i>7xsl</i>			1.00	103.10		103.10
16	6	RETAINER, RR BUMPER <i>7xsl</i>			1.00	103.10		103.10
17	7	SUPPORT, RR BUMPER <i>7xsl</i>			1.00	113.30		113.30
18	8	SUPPORT, RR BUMPER <i>7xsl</i>			1.00	113.30		113.30
19	9	PANEL SUB-ASSY, BODY <i>7xsl</i>			1.00	660.50		660.50
20	0	COVER, DECK TRIM, RR <i>7xsl</i>			1.00	204.80		204.80
21	1	PANEL SUB-ASSY, BACK <i>7xsl</i>			1.00	2025.90		2025.90
22	2	WEATHERSTRIP, BACK <i>7xsl</i>			1.00	465.30		465.30
23	3	GLASS, BACK DOOR <i>7xsl</i>			1.00	1379.30		1379.30
24	4	DAM, WINDOW GLASS <i>7xsl</i>			1.00	40.10		40.10
25	5	CLIP, BACK WINDOW <i>7xsl</i>			1.00	14.70		14.70
26	6	CLIP, BACK WINDOW <i>7xsl</i>			1.00	14.70		14.70
27	7	MOULDING, BACK <i>7xsl</i>			1.00	42.70		42.70
28	8	MOULDING, BACK <i>7xsl</i>			1.00	9.80		9.80
29	9	SPACER, BACK WINDOW <i>7xsl</i>			1.00	9.80		9.80
30	0	LOCK ASSY, BACK DOOR <i>7xsl</i>			1.00	647.90		647.90
31	1	PLATE, BACK DOOR <i>7xsl</i>			1.00	63.10		63.10
32	2	SENSOR, ULTRASONIC <i>7xsl</i>			2.00	503.90		1007.80
33	3	CLIP, ULTRASONIC <i>7xsl</i>			4.00	16.60		66.40
34	4							
For & on behalf of				Customer's Signature		Total		
Borneo Motors (Singapore) Pte Ltd				Please acknowledge receipt of vehicle		Charge Summary		
				Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		



Co. Reg No. : 196700080Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6831 1188

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tan Chee Keong (Chen Zhiqiang) 10 Lorong Ampas #15-05 Singapore 328784 Mobile: 80878807		
			Document No. 0				
			Document Date 26/10/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2024	MXPL10R	MXSUB E1	26/04/2024	SNS4448A	0	34203	79/DS/SNS4448A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDBBBA320L001625	M15AY955689	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
35	5	T89997-30100 ANTENNA, ELECTRICAL	1.00	100.00		100.00	
36	6	T21000-20 SIKI 182010 SIKI TACK GO! (BLA M. /	2.00	108.00		216.00	
37	7	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Handwritten notes:</i> 4690010068 5 days 01/11/24 Res 54 part							
For & on behalf of			Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd			Parts 8,427.70 Labour 7,710.64 Sublet 480.00 Lubrication/Fluid 0.00 Others 0.00		GST 9.00% 1,495.65 Less 0.00 Amount Due 18,113.99		