



JOYRIDE.CO PTE. LTD.
50 SERANGOON NORTH AVENUE 4 FIRST CENTRE #01-24
555856
Singapore

QUOTATION

QU-0002

Not Authorized
L1 Pay @ 125c/hr
Running After Paym

Date : 27-11-2024

Delivery Date : 27-12-2024

Ref# :

CB150R (FBN2066A)

#	Item	Qty	Rate	Amount	
1	Handle Bar	1.00 pcs	65.00	<i>DIY</i> 65.00	✓
2	Brake Lever	1.00 pcs	18.00	<i>DIY</i> 18.00	✓
3	Clutch Lever	1.00 pcs	22.00	<i>ln</i> 22.00	X
4	Mirror One Set	1.00 pcs	80.00	<i>Ad</i> 80.00	✓
5	OBV	1.00 pcs	250.00	<i>Ad</i> 250.00	✓
6	Front Mudguard	1.00 pcs	65.00	<i>ln</i> 65.00	X
7	Front Fork Replacement	1.00 pcs	700.00	<i>ln</i> 700.00	✓
8	Front Rim Replacement	1.00 pcs	250.00	<i>ln</i> 250.00	X
9	Front Brake Disc	1.00 pcs	90.00	<i>ln</i> 90.00	X
10	Left Shroud Cover	1.00 pcs	60.00	<i>mycat</i> 60.00	✓
11	Radiator	1.00 pcs	180.00	<i>ln</i> 180.00	✓
12	Tank Cover	1.00 pcs	150.00	<i>ln</i> 150.00	X
13	Gear Pedal	1.00 pcs	25.00	<i>DIY</i> 25.00	✓
14	Foot Rest	1.00 pcs	28.00	<i>Ad</i> 28.00	✓
15	Guard (Bracket)	1.00 pcs	45.00	<i>ln</i> 45.00	X
16	Left Pillion Foot Rest	1.00 pcs	20.00	<i>ln</i> 20.00	X
17	Front Number Plate	1.00 pcs	20.00	<i>ln</i> 20.00	✓
18	Front Signal Light Set	1.00 pcs	45.00	<i>Ad</i> 45.00	✓
19	Handle Grip	1.00 pcs	25.00	<i>ln</i> 25.00	✓

#	Item	Qty	Rate	Amount
20	Left Switch	1.00 pcs	80.00	1m 80.00 X
21	Rear Top Box	1.00 pcs	120.00	nd 120.00 ✓
22	Headlight Stay	1.00 pcs	35.00	r 35.00 X
23	Labour	1.00 pcs	600.00	600.00 15d
Items in Total 23.00			Sub Total	2,973.00
			Total	SGD 2,973.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: