

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlumc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN AH SENG  
BLK 463 ANG MO KIO AVE 10 #03-1096  
SINGAPORE 560463

ATTN:

Estimate No: MC1904650  
Date: 29 Oct 2024  
Policy No: V5014059  
Veh Reg No: SNE5147K  
Make/Model: MERCEDES BEN  
GLA200 SUV AMG LINE

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 27/10/2024  
TP Veh Reg No: GBK4139B

86376.50

NOT Authorized Kenneth 10:50 am  
Recovery B6 passy 30/10/24  
21/10/20 4 days

## Estimate Repair Cost to Vehicle No :SNE5147K

| Description                                                                                                                                                          | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------|---------------|
| PRICE QUOTE IN NETT PRICE                                                                                                                                            |          |                   |               |
| SPARE PARTS                                                                                                                                                          |          |                   |               |
| 1 REAR DOOR RH                                                                                                                                                       | 1 PC     | 2,300.00          | ✓             |
| 2 REAR DOOR LOWER GARNISH WITH CHROME MOULDING RH                                                                                                                    | 1 PC     | 235.00            | ✓             |
| 3 REAR DOOR WHEEL ARCH RH                                                                                                                                            | 1 PC     | 235.00            | ✓             |
| 4 REAR DOOR LOCK RH                                                                                                                                                  | 1 PC     | 365.00            | X             |
| 5 REAR DOOR RUBBER @ DOOR RH                                                                                                                                         | 1 PC     | 330.00            | ✓             |
| 6 REAR FENDER WHEEL ARCH RH                                                                                                                                          | 1 PC     | 135.00            | ✓             |
| 7 REAR WHEEL HUB WITH BEARING RH                                                                                                                                     | 1 PC     | 505.00            | X             |
| 8 REAR KNUCKLE ARM RH                                                                                                                                                | 1 PC     | 1,500.00          | X             |
| 9 SPORT RIM RHR                                                                                                                                                      | 1 PC     | 2,350.00          | ✓             |
|                                                                                                                                                                      |          | 7,955.00          | 7,955.00      |
| Special Nett                                                                                                                                                         |          |                   |               |
| 10 TYRE RHR check price                                                                                                                                              | 1 PC     | 0.0000            | X             |
| 11 INNER SEAL                                                                                                                                                        | 1 PC     | 20.00             | X             |
| 12 SEALANT                                                                                                                                                           | 1 PC     | 40.00             | X             |
|                                                                                                                                                                      |          | 60.00             | 60.00         |
| LABOUR                                                                                                                                                               |          |                   |               |
| 13 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.                                                                                                                           | 1 PC     | 80.00             | 601           |
| 14 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR. RHR                                 | 1 PC     | 120.00            | 601           |
| 15 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS. RHR                                                                                                                | 1 PC     | 60.00             | X             |
| 16 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. RHR                                                                                                            | 1 PC     | 120.00            | X             |
| 17 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.                                                                                                              | 1 PC     | 60.00             | X             |
| 18 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT                                                                                                    | 1 PC     | 200.00            | 2thot         |
| 19 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.                                                                                                                     | 1 PC     | 30.00             | ✓             |
| 20 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR FENDER RH, REAR BUMPER & INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | 1 PC     | 500.00            | 601           |
| 21 TO SPRAY REAR DOOR RH, REAR FENDER RH, REAR BUMPER                                                                                                                | 1 PC     | 700.00            | 601           |
|                                                                                                                                                                      |          | 1,870.00          | 1,870.00      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: