

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
no
mokus

29/10/24

2 days 2/s a 3200/
the photo after repair

VEHICLE No: SNU 7733X

1PC	FRONT BUMPER	873.90	cur/ton	\$1,180.00	—
1PC	FRONT BUMPER LOWER SPOILER		cre	\$1,200.00	—
1PC	FRONT BUMPER BEAM		na	\$488.00	X
1PC	FRONT BUMPER SIDE RETAINER O/S		but	\$45.00	—
1SET	FRONT BUMPER CLIPS	35.00	na	\$50.00	—
1PC	HEADLAMP O/S	1480.00	cro	\$2,450.00	—
1PC	HEADLAMP LOWER BRACKET O/S		su	\$86.30	X
1PC	FRONT SUPPORT PANEL		~	\$566.20	X
1PC	FRONT FENDER O/S		~	\$650.00	X
1PC	FRONT FENDER INNER SHIELD O/S	242.50	tu	\$266.50	—
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	35.00	na	\$50.00	—
1PC	FRONT LOWER ARM O/S		~	\$482.50	X
1PC	FRONT KNUCKLE ARM O/S		~	\$455.20	X
1PC	FRONT KNUCKLE ARM BEARING O/S		~	\$250.00	X
1PC	FRONT SPORT RIM 17 INCH O/S		~	\$1,200.00	X
				\$9,419.70	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	1~	\$180.00 X
TO SPRAY RUST PROOFING	1~	\$80.00 X
TO REFILL AIR CON GAS	1~	\$120.00 X
TO CONDUCT WHEEL ALIGNMENT	~	\$150.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$680.00 280
TO PUTTY & SPRAY PAINTING		\$900.00 600
TOTAL		\$11,579.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-3911-4
202
3129-12
900
4029-12
202
3223