

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

Not withold
11 Day @ 2200/h
Heavy Area Paint
4- days

Estimate : TP24/034

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Date : 16/11/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 16/11/2024
 Claim No. : D24008620MFCT/CTPL/TPD-2
 Reference : LYB/SGY4674S/MSFirst/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|---|----------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 2 | REAR BUMPER | | |
| 3. | 2 | REAR BUMPER BRACKETS | | |
| 4. | 1 | REAR BUMPER RETAINER | | |
| 5. | 1 | REAR LID | | |
| 6. | 1 | REAR LID RUBBER | | |
| 7. | 1 | REAR LID LOCK (UPPER) | | |
| 8. | 1 | REAR LID LOCK (LOWER) | | |
| 9. | 1 | REAR TAILEND PANEL | | |
| 10. | 2 | REAR TAILEND INNER GARNISH | | |
| 11. | 1 | REAR TAILLAMP LOWER PANEL | | |
| | | REAR BUMPER LIP SPOILER | | |

List Total S\$:
 25.00% Discount S\$:

<i>olsa</i>	70.20	<i>bul/mbrm</i>	501.70	<i>✓</i>
<i>olsori</i>	30.20	<i>a</i>	140.40	<i>✓</i>
			60.40	<i>✓</i>
		<i>n</i>	641.60	<i>x</i>
		<i>im</i>	161.80	<i>x</i>
		<i>pd</i>	90.70	<i>x</i>
		<i>r</i>	42.10	<i>x</i>
		<i>By</i>	666.10	<i>✓</i>
		<i>nd</i>	45.15	<i>✓</i>
	121.60	<i>n</i>	243.20	<i>x</i>
		<i>pa</i>	551.30	<i>x</i>
			3,144.45	
			786.11	
			2,358.34	

- | | | | | |
|----|---|---------------------------|--|--|
| 1. | 1 | NETT ITEMS : | | |
| 2. | 1 | REAR EMBLEM '1.6E' | | |
| 3. | 1 | REAR EMBLEM 'VVTI' | | |
| 4. | 1 | REAR EMBLEM 'COROLLA' | | |
| 5. | 2 | REAR EMBLEM 'ALTIS' | | |
| | | REAR EMBLEM LOGO 'TOYOTA' | | |

Nett Total S\$:

		<i>na</i>	40.20	<i>✓</i>
		<i>na</i>	39.70	<i>✓</i>
		<i>na</i>	51.30	<i>✓</i>
		<i>na</i>	40.20	<i>✓</i>
		<i>na</i>	115.80	<i>✓</i>
			287.20	

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721

Tel No. : 64534177 Fax No. : 64593724

E-Mail : limyewboo@singnet.com.sg

Website : www.limyewboo.com.sg

Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department

Contact : 65073848 Fax No. : 65073849

Estimate : TP24/034

Date : 16/11/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 16/11/2024
 Claim No. : D24008620MFCT/CTPL/TPD-2
 Reference : LYB/SGY4674S/MSFirst/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPECIAL NETT ITEMS :		
1.	4	REAR TAILEND PANEL TEROSTAT SEALANT	54.20	na 216.80 X
2.	1 SET	REAR TAILEND INNER GARNISH CLIPS	2.80	na 12.00 ✓
3.	12	REAR RIVET		na 33.60 X
4.	1 SET	REAR REVERSE SENSOR		na 220.00 X
5.	1	REAR BUMPER LIP SPOILER SEALANT		na 54.20 ✓
6.	1	REAR BUMPER LIP SEALANT STRIP	10.00	na 120.00 ✓
7.	5	REAR BUMPER FASTENER	10.00	na 50.00 ✓
8.	5	REAR BUMPER EXTENSION FASTENER	10.00	na 50.00 X
9.	5	REAR BUMPER EXTENSION GROMMET SCREW		na 50.00 X

		Special Nett Total S\$:		806.60
		LABOUR :		na 80.00 X
		TO CHECK ALIGNMENT ON AFFECTED EXHAUST		120.00 50/
		LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS		150.00 30/
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS		na 80.00 X
		TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID		80.00 20/
		TO CHECK WATER SEEPAGE		
		TO REPAIR, PANEL BEAT, CUT & WELD ON AFFECTED PANEL,		

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP24/034

Date : 16/11/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 16/11/2024
 Claim No. : D24008620MFCT/CTPL/TPD-2
 Reference : LYB/SGY4674S/MSFirst/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR TO REPLACE THE ABOVE PARTS		800.00 <i>600</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, SPOILER, TAILLAMP LOWER PANEL & SENSOR.		1,000.00 <i>800</i>
		Labour Total S\$:		2,310.00

E. & O.E. Total S\$: 5,762.14


 for LIM YEW BOO SPRAY PAINT CO. 