


Car-n 11/2 nr-36488
PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Hui Roy



Asen-Adrian

-4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1530 U.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rehnd</i>	1	\$ 2,615.00	✓
2	REAR BUMPER STICKY PAD <i>new</i>	4	\$ 30.00	+
3	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 216.00	+
4	REAR BUMPER ADAPTOR - LH <i>Not new</i>	1	\$ 48.00	+
5	REAR BUMPER GUIDE SECTION - LH <i>Damaged</i>	1	\$ 21.00	✓
6	REAR BUMPER LOCKING MECHANISM	1	\$ 75.00	✓
7	REAR BUMPER SPOILER	1	\$ 297.00	+
8	REAR LIGHT REFLECTOR - LH <i>new</i>	1	\$ 49.00	+
9	REAR PARKING AID SENSOR	1	\$ 286.00	+
10	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 11.00	+
11	LED TAILLIGHT - LH <i>cut</i>	1	\$ 1,094.00	✓
12	LED TAILLIGHT TRIM - LH <i>new</i>	1	\$ 36.00	+
13	SUNDRIES		\$ 500.00	-
TOTAL SPARE PARTS			\$ 5,278.00	
TOTAL LABOUR CHARGES			\$ 4,072.00	
GRAND TOTAL			\$ 9,350.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

Adrian Ly
Resurveyed.
HL