



## Supplementary

Estimate No. : **b1 71607**  
 Date Estimated : **25/10/2024**  
 Prepared By : **Yap Mee Key**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Chew Chee Hou Ignatius (Zhou Zhihao**  
**31 FERNVALE ROAD**  
**#08-49**

**SINGAPORE 797417**

**- ACCOUNT - 115**

**United Overseas Insurance Ltd**  
**146 Robinson Road**  
**#02-01 UOI Building**  
**Singapore 068909**

|           |                   |            |              |         |
|-----------|-------------------|------------|--------------|---------|
| REGN. NO. | CHASSI S NO.      | REGN. DATE | MODEL        | M LEAGE |
| SLW4828P  | WBA32AA0405V30936 | 25/08/2022 | X1 sDrive18i | 32714   |

| DESCRIPTION                                                                                                                                                                                                                                                                                                                                             | ORIGINAL PRICE | DISC. % | NETT     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|---------|----------|
| ** To replace rear bumper panel, tail panel, boot lid, rear trim panel, rear carrier, smart opener mounting, rear trim underride protection, rear corner mounting, rear middle trim panel, rear RH LED light in side panel, rear LED light in tailgate, rear spoiler third stoplamp include carrying out other necessary repairs caused by the accident | 5,525.00       |         | 5,525.00 |
| ** To respray boot lid, rear bumper, tail end panel and rear spoiler                                                                                                                                                                                                                                                                                    | 3,267.00       |         | 3,267.00 |
| ** To remove and install rear boot compartment carpets and garnish to facilitate repairs                                                                                                                                                                                                                                                                | 271.00         |         | 271.00   |
| ** To carry out body cavity preservation (x1) (For cut panel)                                                                                                                                                                                                                                                                                           | 531.00         |         | 531.00   |
| * To carry out body cavity preservation (x1) (Per panel)                                                                                                                                                                                                                                                                                                | 118.00         |         | 118.00   |

| DESCRIPTION                      | UNIT PRICE | QTY  | DISC. % | NETT              |
|----------------------------------|------------|------|---------|-------------------|
| # BLIND RIVET NUT M6             | 3.15       | 4.00 | 0.00    | 12.60 <i>nei</i>  |
| # 3M S/F PREMIUM REAR WINDSCREEN | 252.34     | 1.00 | 0.00    | 252.34 <i>nei</i> |
| # EXPANDING NUT                  | 1.10       | 2.00 | 0.00    | 2.20 <i>nei</i>   |

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
 Co Reg No. 197401559W



# Performance Motors

BMW Dealer



## Supplementary

|                                     |        |       |      |        |       |
|-------------------------------------|--------|-------|------|--------|-------|
| # BUMP STOP                         | 3.75   | 10.00 | 0.00 | 37.50  | net / |
| # EXPANDING RIVET BLACK             | 1.50   | 10.00 | 0.00 | 15.00  | net / |
| # THIRD STOPLAMP                    | 202.85 | 1.00  | 0.00 | 202.85 | dis / |
| # BLIND RIVET AVIBVLB               | 1.00   | 50.00 | 0.00 | 50.00  | net / |
| # SCREW (SF PLUS M5X15)             | 1.25   | 10.00 | 0.00 | 12.50  | net / |
| # PUNCH RIVET N4                    | 0.65   | 40.00 | 0.00 | 26.00  | net / |
| # (DG/SL) BODY ADHESIVE K5 (195 ML) | 341.20 | 1.00  | 0.00 | 341.20 | net / |
| # (DG/SL) ACTIVATOR 1 30ML          | 40.50  | 1.00  | 0.00 | 40.50  | net / |
| # (SL/DG) SEALANT D2 290ML          | 45.90  | 1.00  | 0.00 | 45.90  | net / |

### # SUPPLEMENTARY ITEMS

|                                     |           |
|-------------------------------------|-----------|
| Total Labour :                      | 9,712.00  |
| Total Parts :                       | 1,038.59  |
| Total Labour & Parts (before GST) : | 10,750.59 |

#### Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

