

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/11124100535/Unp3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLR 8881Jat Workshop m/s Long Auto Services

of \_\_\_\_\_

Insured: G B B 2063X

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$220k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: 217 812886Veh No: SLR 8881J Yr Regn: 01/10/24Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer Benz GLB 180 c.c. 1332Colour: Black A/C: Insured / Std / NI / NASp.Reading: 3813 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WIN 2476842W 378794Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/55 R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 29/10/24 D.O.I. 30/10/24

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear & Rear w/screen shattered

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 22k.

18/11/24 new car 260k  
4/5 @ 14,600 in bond MR 1cc (Red. \$18264.53, 55%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) ☐ : Interview (\$ \_\_\_\_\_) ☐ : Tech. Invs (\$ \_\_\_\_\_) ☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	688D
<b>Vehicle Details</b>	
Vehicle No.:	SLR8881J
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLB 180 PROGRESSIVE LINE
Primary Colour:	Black
Manufacturing Year:	2024
Engine No.:	28281480181264
Chassis No.:	W1N2476842W378794
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$40,861.00
Original Registration Date:	01 Aug 2024
First Registration Date:	01 Aug 2024
Transfer Count:	0
Actual ARF Paid:	\$49,636.00 24818
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jul 2034
PARF Rebate Amount:	\$37,227.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Jul 2034
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$90,889.00
COE Rebate Amount:	\$88,641.00
<b>Total Rebate Amount:</b>	<b>\$125,868.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 30 Oct 2024

OK

## Mercedes-Benz GLB-Class GLB180 Progressive 7-Seater

**Sold** 19-Apr-2023  
(8yrs 5mths COE left)   
[View](#)  
[Similar](#) 1,332 cc 2 Owners

Call to view now! Excellent condition, as good as buying new but with huge savings! Trade in welcomed! Flexible loan schemes available to suit your needs. Don't commit to others before viewing this beauty!

Euro Performance Asia Pte Ltd|Posted 07-Oct-2024

☐ Compare

**SOLD**

PREMIUM AD



## Mercedes-Benz GLB-Class GLB180 Progressive

**\$218,888** \$21,500 /yr 27-Dec-2023  
(9yrs 1mth COE left) 6,900 km   
Instl. \$1,835 /mth 1,332 cc 1 Owner

C&C unit. Fully maintained by C&C. 1 owner only, well maintained by careful owner, \$0 downpayment! Fast loan approval with flexible financing! Low interest rate! We welcome Vicom/STA evaluation! WhatsApp/call us to book your ride now!

Posted 07-Oct-2024

☐ Compare

## Mercedes-Benz GLB-Class GLB180 Progressive

**Sold** 30-Nov-2023  
(9yrs COE left) 1,332 cc  
[View](#)  
[Similar](#) 1 Owner

C&C unit. Fully maintained by C&C. 1 owner only, well maintained by careful owner, \$0 downpayment! Fast loan approval with flexible financing! Low interest rate! We welcome Vicom/STA evaluation! WhatsApp/call us to book your ride now!

Posted 07-Oct-2024

☐ Compare

**SOLD**



## Mercedes-Benz GLB-Class GLB180 Progressive 7-Seater

**\$210,800** \$23,040 /yr 10-Jan-2023  
(8yrs 2mths COE left) 18,000 km 1,332 cc 1 Owner  
Instl. \$1,767 /mth

Meticulous single owner unit! Selling due to EV preferred! Accident free! Verified battery recently replaced! Definitely zero repairs needed, full comprehensive engine/gearbox warranty available! 100% loan available at 2.48% per annum! 1 to 1 exchange without cash top up! Hurry and call our sales advisers for more information! Best price guarantee!

Paragon Motor Pte Ltd|Posted 05-Oct-2024

☐ Compare

PREMIUM AD

## Mercedes-Benz GLB-Class GLB180 Progressive

**Sold** 30-Jun-2023  
(8yrs 7mths COE left)   
[View](#)  
[Similar](#) 1,332 cc 1 Owner

5 years C&C warranty, 10 years engine warranty, fully maintained at agent, call our sales consultant for an appointment to view.

Wearnes Pre-Owned|Posted 04-Oct-2024

☐ Compare

**SOLD**

Compare

# HONG AUTO SERVICES

2 Kaki Bukit Ave 2, #01-28, Singapore 417921  
Tel: 6747 6436 / Fax: 6746 8868 / HP: 9853 5155  
Email: tchong4281@gmail.com

Not Authorized  
du  
Moran S  
30/10/24  
5 days. d/s 14,600  
Wahph. Attemp

Vehicle number: SLR8881J

Vehicle Made & Model: MERCEDES-BENZ GLB 180

Qty	List Items	Amount \$
1	Tailgate <i>Bodily DD</i>	4,881.22 ✓
1	Tailgate windshield <i>shattered</i>	1,322.51 ✓
2	Tailgate windshield side garnishes - L/R @ 211.50 <i>See</i>	423.00 X
1	Tailgate top spoiler <i>11</i>	1,153.21 X
1	Tailgate wiper arm <i>Damage</i>	180.93 ✓
1	Tailgate wiper arm cover <i>n.s</i>	55.63 ✓
1	Tailgate wiper motor <i>Damage</i>	591.66 ✓
2	Tailgate lamps - L/R @ 551.23 <i>See/CNE 427.14x2=854.28</i>	1,102.46 ✓
2	Tailgate licence lamps @ 89.95 <i>11</i>	179.90 X
1	Tailgate opening switch <i>Damage</i>	280.63 ✓
1	Tailgate inner lock <i>Damage</i>	755.13 ✓
1	Tailgate inner top trim <i>11</i>	311.26 X
1	Tailgate inner trim board <i>CNE/CNE</i>	511.62 ✓
1	Tailgate w/strip <i>Two</i>	322.71 ✓
2	Tailgate hinges - L/R @ 85.50 <i>11</i>	171.00 X
2	Tailgate dampers - L/R @ 891.10 <i>11</i>	1,782.20 X
2	Tailgate stoppers - L/R @ 22.60 <i>11</i>	45.20 X
1	Tailgate M/B star <i>11</i>	89.95 ✓
1	Tailgate M/B star clips @ 8.50 <i>11</i>	25.50 ✓
1	Tailgate emblem "GLB 180" <i>11</i>	141.20 ✓
2	Taillamps - L/R @ 894.35 <i>M/S CNE 0/511</i>	1,788.70 126
2	Taillamp lower brackets - L/R @ 86.60 <i>11</i>	173.20 X
1	Rear bumper - Top <i>Dis</i>	1,655.93 ✓
1	Rear bumper chrome plate - Top <i>Dis</i>	611.42 ✓
1	Rear bumper CTR pad <i>Torn</i>	811.33 ✓
1	Rear bumper bottom chrome trim <i>CNE</i>	1,471.43 ✓
1	Rear bumper bottom cover - CTR <i>Torn</i>	681.62 ✓
1	Rear bumper reflector - LH <i>See</i>	112.10 X
4	Rear bumper PDC sensors - LH @ 281.33 <i>M/S CNE 0/511</i>	1,125.32 2PCS
1	Rear bumper PDC sensor wire harness <i>See</i>	411.20 X
1	Rear bumper reinforcement <i>Dis</i>	1,055.90 ✓
2	Rear bumper lower brackets @ 110.20 <i>M/S CNE 0/511</i>	220.40 1PC
2	Rear bumper side retainers - L/R @ 115.60 <i>11</i>	231.20 X
1	Rear end panel <i>R</i>	1,015.60 X
1	Rear end panel trim <i>See</i>	280.93 X
1	Rear exhaust chrome trim - LH <i>See/CNE</i>	485.91 ✓
1	Rear exhaust insulator <i>11</i>	281.60 X
1	Rear exhaust silencer <i>See</i>	1,895.60 X
2	Rear fender ARC garnishes - L/R @ 399.62 <i>See</i>	799.24 X

Vehicle number: SLR8881J

Vehicle Made & Model: MERCEDES-BENZ GLB 180

1	Rear foot activated sensor	<i>one</i>	391.23	✓
1	Rear fender inner trim - LH	<i>11</i>	661.59	X
<b>Sub-total</b>			30,488.37	
<b>Less 10%</b>			3,048.84	
<b>Total List</b>			27,439.53	

**Special Nett Items**

1 set	Rear windscreen sealant	<i>nu</i>	120.00	<i>40</i>
1	Rear windshield solar film	<i>nu</i>	280.00	<i>200</i>
1	Rear recorder camera	<i>su</i>	550.00	<i>x</i>
1	Rear reverse camera	<i>su</i>	420.00	<i>x</i>
1 set	Rear bumper clip	<i>nu</i>	60.00	<i>40</i>
1 set	Rear no. plate	<i>scrl</i>	65.00	<i>40</i>
<b>Total Special Nett</b>			1,495.00	

**Labour Charges**

To check rear electrical wiring	50.00	<i>20</i>
To remove, refix tailgate windshield	180.00	<i>120</i>
To remove, refix rear interior trims to assist repair	150.00	<i>60</i>
To vaccuum, waxing and cleaning interior	<i>11</i> 180.00	<i>x</i>
To diagnose, erase fault memory after reappear	350.00	<i>80</i>
To respray undercoating	120.00	<i>30</i>
To respray painting & etc	1,400.00	<i>800</i>
Panel beating, cut, weld, remove & replacing above parts	1,500.00	<i>550</i>
<b>Total Labour</b>	3,930.00	

**ESTIMATE PARTS & LABOUR GRAND TOTAL \$**

**32,864.53**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

7-18148-36  
102  
16333.53  
320  
1660  
18313.53  
212  
14650.