

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24110003/ENH3M4
Date: 07/11/2024**REFERENCE**

| | | | |
|------------------------------|--------------------------------------|-----------------------------|----------|
| Handling Insurer: | Tokio Marine Insurance Singapore Ltd | Policy No: | MZC05214 |
| Claimant Vehicle No : | SH6503J | Insured Vehicle No : | GBJ4907G |
| Date of Loss: | 29/10/2024 | Nature of Claim: | TP |
| | | Claim No: | M2406362 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SH6503J | Engine No: | G4LEJU192044 |
| Make & Model: | HYUNDAI AE IONIQ HEV, 1.6 DCT (A) | Chassis No: | KMHC851CVKU141542 |
| Reg. Date: | 02/04/2019 (Man. Year: 2018) | Odometer: | 592390 km |
| Colour: | Blue | | |
| Engine Capacity: | 1580 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|---------|
| General Condition: | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | Average |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | West Lake 6 mm | Rear Left Side: | West Lake 6 mm |
| Front Right Side: | West Lake 6 mm | Rear Right Side: | West Lake 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 6,054.36 | 2,362.20 | 3,692.16 | 60.98 |
| Miscellaneous Items | 12.00 | 12.00 | 0.00 | 0.00 |
| Labour | 3,775.00 | 3,005.00 | 770.00 | 20.40 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 9,841.36 | 5,379.20 | 4,462.16 | 45.34 |
| Approved Total (Overridden) (S\$) | | 4,300.00 | | |
| (S\$) | 9,841.36 | 4,300.00 | 5,541.36 | 56.31 |
| + GST 9.00/9.00% (S\$) | 885.72 | 387.00 | 498.72 | 56.31 |
| Nett Amount (S\$) | 10,727.08 | 4,687.00 | 6,040.08 | 56.31 |

INSPECTION

| | | |
|-----------------------------|------------------------------|---|
| Date of Assignment: | 30/10/2024 Present Location: | ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) |
| Date Inspected: | 01/11/2024 Inspected At: | 59 LOYANG DRIVE SINGAPORE 508969 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

| | |
|---|--|
| Reference | |
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 07 Nov 2024) |
| Parts: 143 | HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SH6503J) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRT BUMPER ASSY | Repair | 481.10 FL | *- FL |
| 2 | 10 | | *FRT BUMPER CLIPS | Not Necessary | 22.00 FL | *- FL |
| 3 | 1 | | *FRT BUMPER SIDE BRACKET LH | Not Necessary | 35.00 FL | *- FL |
| 4 | 1 | | *FRT FENDER LH | Dented | 588.80 FL | *588.80 FL |
| 5 | 1 | | *FRT FENDER EMBLEM LH | Necessary | 26.60 FL | *26.60 FL |
| 6 | 1 | | *FRT DOOR ASSY LH | Dented | 1,797.20 FL | *1,797.20 FL |
| 7 | 1 | | *REAR DOOR ASSY LH | Repair | 1,789.90 FL | *- FL |
| 8 | 1 | | *REAR FENDER LH | Repair | 1,768.30 FL | *- FL |
| 9 | 1 | | *REAR REAR BUMPER ASSY | Repair | 459.40 FL | *- FL |
| 10 | 10 | | *REAR REAR BUMPER CLIPS | Not Necessary | 22.00 FL | *- FL |
| 11 | 1 | | *FRT DOOR COMFORT LOGO | Necessary | 75.00 F | *75.00 F |
| 12 | 1 | | *REAR DOOR APPS LOGO | Necessary | 80.00 F | *80.00 F |
| 13 | 1 | | *PATROL STICKER | Not Necessary | 30.00 F | *- F |
| 14 | 1 | | *WHEEL RIM CAP FRT | Cut | 346.40 FL | *346.40 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 7,521.70 | 2,914.00 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 1,467.34 | 551.80 |
| Total Parts (\$) | 6,054.36 | 2,362.20 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|-----------------------|--------------|
| Miscellaneous Items | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 12.00 | 12.00 |
| | | | Sub Total (\$) | 12.00 |
| | | | | 12.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|-----------------------------|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 1,600.00 | 1,140.00 |
| 2 | SPRAYPAINT CHARGES | New | 1,800.00 | 1,680.00 |
| 3 | TUFF KOTE | New | 50.00 | 20.00 |
| 4 | CHECK WIRING | New | 50.00 | 30.00 |
| 5 | TRANSFER DOOR PARTS | New | 120.00 | 30.00 |
| 6 | REMOVE/REFIX REVERSE SENSOR | New | 50.00 | 0.00 |
| 7 | TOWING CHARGES | New | 105.00 | 105.00 |
| | | | Gross Labour Cost (\$) | 3,775.00 |
| | | | | 3,005.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >