

Paint Work

SYSTEM AZT

Time Basis 10 WU/h
WU Price SGD

Code

Description

7.0

FRONT GRILLE NEW PART PAINT K1R

Paint Material Per Part

Price SGD

Code

Description

33.21

23.73

0900

FRONT PANEL CPL NEW PART PAINTING

0410

FRONT GRILLE NEW PART PAINT K1R

Labour Cost - Paint

Hrs

WU

Price SGD

Factor

42.00 SGD/h

34.0

Time Paint

1.70

17.0

71.40

Preparation Main Work Metal

0.30

3.0

12.60

Preparation Comp. Work Plastic

5.40

54.0

226.80

Total

10 WU/h

Price SGD

Material Cost - Paint

33.21

New Part Painting

23.73

New Part Painting - Plastic K1R

18.10

Material-constant Metal

9.00

Material-constant Plastic

84.04

Total

Spare Parts

prices as at 2015-06-01

Code	Description	Part Number	Part Source	Price SGD
0281	FRONT BUMPER	MC978515	Original	750.00
0284	R/F BUMPER BRACKET	MK617974	Original	120.00
0290	R/F BUMPER CORNER	MK617989	Original	280.00
0410	FRONT GRILLE	MC975208	Original	440.00
0431	FRONT MANUFACT	MK546616	Original	65.00
	BADGE			
0432	BADGE	MK546617	Original	0.00
0433	BADGE	MK675497	Original	65.00
0562	RIGHT HEADLAMP ASSY	MK580526	Original	350.00
0678	R/F INDICATOR	MK581220	Original	220.00
0718	R/POSITION LAMP	MK580530	Original	150.00
0900	FRONT PANEL CPL	ML230262	Original	750.00
2206	R/F STEP <i>cm</i>	MK677507	Original	320.00
1000	clip RH @6*\$6	F/corner panel	Original	36.00
1001	lower rubber RH	Headlamp	Original	18.00
1006	Steering box <i>bo</i>	Steering box	Original	1,300.00
Savings				0.00
Subtotal				4,864.00
Fixed Sundry Parts Price				80.00
Total				4,944.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts