



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS

Ref: CS/INC24110016/Avh3m4(N)

Date: 17/03/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 2929L	Veh. Inspected	SMW 3459R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302093-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	01/11/2024

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI OUTLANDER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GF7W0700674	Colour	BRONZE
Odometer	54729 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55R18	TOYO	6 mm
L/H Front Tyre	225/55R18	TOYO	6 mm
R/H Rear Tyre	225/55R18	TOYO	6 mm
L/H Rear Tyre	225/55R18	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2024	Inspect Date / Time	01/11/2024 (03:20 PM)
Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**