

(08/11/13) W07

ASS. REC. BY:

REF: CS/CT124110017/Rnh3

653C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKV 8302E

at Workshop m/s AVANTAGE

of 48, TOH KUAN RD CARI

Insured:

CT1

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

19K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKV 8302E

Yr Regn: 2015 / OCT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI ELANTRA 1.6 AT c.c 1591

Colour:

RED

A/C: Insured / Std / NI / NA

Sp. Reading:

95493

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM 40441 CM 9U 625 258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/10/24

D.O.I.

01/11/24

Survey held at

TOH KUAN

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 6K

30/12/24 submit preli report (withdraw claim) at TP wksp

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS \$

) Photos

) Other

TOTAL



VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Vehicle Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 30-Oct-2024

Vehicle Num : SKV8302E

Make/Model : HYUNDAI / ELANTRA 1.6 AT ABS D /AI

Chassis No : KMHDH41CMGU625258

S/N	PARTS	QTY	PRICE	TOTAL
1	Front bumper <i>cm</i>	1	\$ 439.46	\$ 439.46
2	Front bumper bracket Lh <i>m</i>	1	\$ 20.52	\$ 20.52
3	Front bumper upper bracket Lh <i>*?</i>	1	\$ 30.78	\$ 30.78
4	Front bumper inner bracket Lh <i>*?</i>	1	\$ 17.11	\$ 17.11
5	Front bumper inner bracket Rh <i>*?</i>	1	\$ 17.11	\$ 17.11
6	Front fender Lh <i>buc</i>	1	\$ 405.69	\$ 405.69
7	Front fender bracket Lh <i>m</i>	1	\$ 51.30	\$ 51.30
8	Front wheelhouse cover Lh <i>fun</i>	1	\$ 82.08	\$ 82.08
9	Front headlamp Lh <i>sa</i>	1	\$ 1,267.57	\$ 1,267.57
10	Front headlamp bracket Lh <i>X nn</i>	1	\$ 92.95	\$ 92.95
11	Front door upper hinge Lh <i>*?</i>	1	\$ 43.94	\$ 43.94
12	Front door lower hinge Lh <i>*?</i>	1	\$ 43.94	\$ 43.94
13	Side mirror assembly Lh <i>* JAN - photo</i>	1	\$ 777.42	\$ 777.42
14	Interior rear view mirror <i>cm</i>	1	\$ 111.15	\$ 111.15
15	Front wheel knuckle Lh <i>?</i>	1	\$ 304.21	\$ 304.21
16	Front wheel bearing Lh <i>?</i>	1	\$ 116.28	\$ 116.28
17	Front shock absorber Lh <i>?</i>	1	\$ 236.60	\$ 236.60
18	Front shock absorber mounting Lh <i>?</i>	1	\$ 81.12	\$ 81.12
19	Front shock absorber spring seat Lh <i>?</i>	1	\$ 34.22	\$ 34.22
20	Front shock absorber upper pad Lh <i>?</i>	1	\$ 39.33	\$ 39.33
21	Front shock absorber lower pad Lh <i>?</i>	1	\$ 30.78	\$ 30.78
22	Front lower arm Lh <i>?</i>	1	\$ 194.35	\$ 194.35
23	Front tie rod end Lh <i>?</i>	1	\$ 61.56	\$ 61.56
24	Front tie rod rack Lh <i>?</i>	1	\$ 76.95	\$ 76.95
25	Sport rim <i>lt</i>	1	\$ 816.32	\$ 816.32 <i>s/n-400</i>
Total Parts				\$ 5,392.74
LESS 20%				\$ 1,078.55
TOTAL AMOUNT				\$ 4,314.19
MISCELLANEOUS ITEM				
1	Sunderies <i>m</i>		\$ 62.50	\$ 62.50 <i>20</i>
2	Front bumper clips <i>m</i>	10	\$ 3.00	\$ 30.00
3	Rivet <i>m</i>	10	\$ 4.50	\$ 45.00
26	Tire <i>m</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
LABOUR				
1	To remove and refitting front bumper, front fender Lh, front headlamp Lh, front door Lh, side mirror assembly Lh and each other.		\$ 960.00	\$ 960.00 <i>700</i>



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	30/10/2024 17:08 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	30/10/2024 04:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	UPPER BUKIT TIMAH / JALAN ASAS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV8302E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	NG KOK IE
NRIC No	SXXXX683C
Email Address	NGKOKIE919@YAHOO.COM
Mobile Phone No	(Phone) +65-91883167
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Elantra
Variant	1.6 AT ABS D /AB 2WD 4DR
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591
Vehicle Fuel	Petrol
First Registration Date	03/10/2015
Chassis no	KMHDH41CMGU625258
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	24-MR005025-R04

DRIVER



Name of Driver	NG KOK IE
NRIC No	SXXX683C
Date Of Birth	02/03/1967
Occupation	Indoor
Driving Pass Date	30/03/1990
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	34 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91883167
Alt. Phone Number	-
Email Address	NGKOKIE919@YAHOO.COM
Address	60 CHESTNUT AVE #12-02 TREEHOUSE
Address complement	-
Postcode	679517
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	SLF4386L
Insurance Company of Other Vehicle Owned by Driver	Liberty Insurance Pte Ltd

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU9083Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	NG KOK IE
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	CHEST PAIN, FRACTURED ON CHEST RID.
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-





SINGAPORE POLICE FORCE



T/20241030/7052

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20241030/7052

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NG KOK IE	ID No.	S2571683C
Related Vehicle	SKV8302E (Motor car)	Contact No.	91883208
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	30/10/2024	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	Slight
Driver			
Name	NG KOK IE	ID No.	S2571683C
Related Vehicle	SKV8302E (Motor car)	Contact No.	91883167
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details

I was driving straight along Upper Bukit Timah Road toward city at middle lane about 4:15am. The car no SLU9083Z driver drove parallel suddenly cut into my lane, both cars collided at left side front passenger seat of my car (SKV 8302E) at Upper Bukit Timah Road / Jalan Asas. (near Railway mall) After he hit on my car, he drove his car straight to the Chia Eng Say Road near Rail Mall open car park (refer to the picture car location). I also drove my car parked near Jalan Asas road side, called for assistance

I have suffered chest pain, my wife drove me to NUH A&E, fractured on chest rib, was hospitalised for treatment.

Another party Driver name: Casper Tan Jun Kai, NRIC No: S8627601A



Hyundai Elantra 1.6A

\$18,000 Instalment \$1,426/mth

Shortlist

Get Warranty

Loan Calculator



Overview Photo Research

Depreciation	<i>i</i> \$13,950 / year
Reg. Date	04-Sep-2015 (10mths COE left)
Manufactured	<i>i</i> 2015
Mileage	-
Transmission	Auto
Engine Cap	1,591 cc
Road Tax	<i>i</i> \$738 / year
Power	97.0 kW (130 bhp) View specs of the Hyundai Elantra (2011-2014)
Curb Weight	<i>i</i> 1,292 kg
COE	<i>i</i> \$57,498
OMV	<i>i</i> \$12,766
ARF	<i>i</i> \$12,766
Dereg Value	<i>i</i> \$11,172 as of today
No. of Owners	<i>i</i> 1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	683C

Vehicle Details

Vehicle No.:	SKV8302E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	G4FGFU024283
Chassis No.:	KMHDH41CMGU625258
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$15,223.00
Original Registration Date:	03 Oct 2015
First Registration Date:	03 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$15,223.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2025
PARF Rebate Amount:	\$7,611.00

Intended COE Rebate Details

COE Expiry Date:	02 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$5,108.00
Total Rebate Amount:	\$12,719.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 30 Oct 2024

OK