

# SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Authorized  
in  
moray  
30/10/24  
d/s #5400  
telephone repair  
6 days

VEHICLE NUMBER: GBB8964G

MAKE & MODEL: NISSAN CABSTAR

NOT item

FRONT WINDSCREEN RUBBER	11		\$150.37	X
FRONT WIPER PANEL GARNISH	11		\$467.30	X
FRONT HEADLAMPS L/R X2	n/s n 10 / 1500	484.20	\$1,412.40	12C
FRONT PANEL	11		\$1,634.20	X
FRONT CORNER PANEL L/R X2	11		\$912.80	X
FRONT GRILLE	11		\$511.30	X
FRONT GRILLE LOGO	11		\$68.20	X
FRONT BUMPER	cur / 02		\$725.40	✓
FRONT BUMPER BRACKET L/R X2	11		\$547.20	X
FRONT BUMPER FOG LAMP COVER L/R X2	11		\$70.00	X
FRONT BUMPER REINFORCEMENT	11		\$745.20	X
CABIN REAR PILLAR RH	R		\$828.10	X
TAILGATE	DD / Bent	1688.30	\$1,831.40	✓
TAILGATE NISSAN STICKER	211		\$158.30	✓
TAILGATE HINGES X3	11		\$233.10	X
TAILGATE SIDE LOCK RH	Bent	150.20	\$200.10	✓
REAR SIDE GATE RH	R		\$3,243.00	X
REAR SIDE GATE HINGES RH X5	11		\$43.00	X
REAR SIDE GATE LOWER MEMBER RH	R		\$823.10	X
TAIL LAMP RH	CR	210.90	\$412.10	✓
END PANEL	DD / Bent	645.20	\$721.40	✓
END PANEL SIDE BRACKET RH	Bent		\$141.30	✓
END PANEL SIDE BRACKET RUBBER STOPPER RH X2	CR	50	\$100.00	12C
REAR NUMBER PLATE BRACKET	Bent		\$124.30	✓
REAR NUMBER PLATE LAMP	11		\$68.10	X
REAR CHASSIS FRAME RH	R		\$1,443.10	X
FLOOR PANEL	R		\$2,015.20	X
SPARE TYRE BRACKET	11		\$284.50	X
SPARE TYRE LOCK BRACKET	11		\$314.60	X
REAR EXHAUST MUFFLER	R		\$845.60	X
REAR EXHAUST MUFFLER BRACKET X2	CR / 1000	68.50	\$188.60	12C
			\$21,263.27	
		Less 10%	\$2,126.33	
			\$19,136.94	

FRONT PANEL SEALANT	11		\$80.00	X
FRONT GRILLE CLIPS	11		\$40.00	X
FRONT NUMBER PLATE	Bent		\$700.00	30
REVERSE SENSOR SET	11		\$280.00	X
REAR NUMBER PLATE	Bent		\$50.00	30
REAR LOWER STEP BAR	Bent		\$700.00	300

TAILGATE 70KM/H STICKER	neu	\$50.00	10
TAILGATE 13 PAX STICKER	neu	\$50.00	10
		<u>\$1,950.00</u>	
TO REMOVE & REFIT FRONT WINDSCREEN	1x	\$150.00	X
TO CHECK FRONT WIRING & HEADLAMP LEVELING		\$60.00	
TO CHECK REAR WIRING		\$50.00	30
TO REPLACE REAR REVERSE SENSOR	1x	\$120.00	X
TO REPLACE, STRAIGHTEN AND ALIGN BOTH REAR CHASSIS MEMBERS		\$1,200.00	400
TO PROVIDE LABOUR, WORKMANSHIP		\$2,000.00	900
TO SPRAY PAINT ON AFFECTED PANELS		\$2,000.00	1000
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	1x	\$120.00	X
RUST PROOFING		\$200.00	50
		<u>\$5,900.00</u>	
Total			\$26,986.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

2- 4446.6  
102  
4001.94  
360  
2380  
6761.94  
202  
5409.