

Date: 01/11/2024  
 Vehicle No: GBL113X  
 Model: TOYOTA HIACE VAN TURBO 5DR MT  
 Chassis: JTFHT02P500251351-2020  
 Reg.Year: 2021

*Not with hold*

*6/1/24 @*

*Running After Pains*

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: GBJ7823U  
 Date of Accident: 30/10/2024  
 Estimator: TING AN  
 Surveyor:

*6 days*

### ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN GLASS	1	<i>Shattered</i>	\$1,714.00 ✓
2	REAR TAILGATE	1	<i>By</i>	\$2,703.00 ✓
3	REAR TAILGATE "TOYOTA" EMBLEM	1	<i>na</i>	\$75.00 ✓
4	REAR TAILGATE CHROME MOULDING	1	<i>wrap</i>	\$197.00 ✓
5	REAR TAILGATE WEATHERSTRIP	1	<i>By</i>	\$395.00 X
6	REAR TAILGATE LOCK	1	<i>na</i>	\$350.00 X
7	REAR TAIL LAMP LH	1	<i>cut</i>	\$450.00 ✓
8	REAR TAIL LAMP LOWER COVER LH	1	<i>na</i>	\$145.00 ✓
9	REAR TAIL BRACKET LH	1		\$60.00 7
10	REAR BUMPER	1	<i>By</i>	\$659.00 ✓
11	REAR BUMPER SIDE BRACKET LH	1	<i>DIY</i>	\$50.00 ✓
12	REAR END PANEL	1		\$475.00 7
13	REAR PANEL LH	1		REPAIR
SUB TOTAL				\$7,273.00
LESS 25%				-\$1,818.25
PARTS TOTAL				\$5,454.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$100.00 400 ✓
2	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
3	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00 700 ✓
4	"70KM" DECAL	1		<i>na</i> \$40.00 700 ✓
5	REAR TAILGATE STRIPE DECAL	1		<i>na</i> \$100.00 60. ✓
S/N TOTAL				\$590.00

Date: 01/11/2024  
 Vehicle No: GBL113X  
 Model: TOYOTA HIACE VAN TURBO 5DR MT  
 Chassis: JTFHT02P500251351-2020  
 Reg.Year: 2021

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: GBJ7823U  
 Date of Accident: 30/10/2024  
 Estimator: TING AN  
 Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,200.00	7
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR TAIL LAMP LOWER COVER LH, REAR END PANEL REAR SIDE PANEL LH & ETC.	\$1,200.00	850
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$100.00	60
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$120.00	20

LABOUR TOTAL      \$2,740.00

TING AN      **TOTAL**      **\$8,784.75**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: