

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT124110026/UVH3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLX419H

at Workshop m/s

Zoom

of

Insured:

XE7014D

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

864k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

1131

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

4016
27A64428P

Vehicle: IN / OUT

Date / Time

Action / Instruction

Dep. 18k.

9/5/25 Long slide only
2/2 # 800 in hand E.L.

Veh No:

SLX419H

Yr Regn:

24/11/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Sport

Make:

Land Rover

Discovery.c.c

1999

Colour

White/Green

A/C:

Insured / Std / NI / NA

Sp. Reading

110084

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SALCAZAG2AH 62/293

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

255/45-R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/10/24

D.O.I.

4/11/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 401G

Vehicle Details

Vehicle No.: SLX419H
Vehicle to be Exported: No
Intended Deregistration Date: 04 Nov 2024
Vehicle Make: LAND ROVER
Vehicle Model: DISCOVERY SPORT 2.0 SI4 SE 7STR
Primary Colour: Green
Manufacturing Year: 2016
Engine No.: 015048021745204PT
Chassis No.: SALCA2AG2GH621293
Maximum Power Output: 177.0 kW (237 bhp)
Open Market Value: \$45,440.00
Original Registration Date: 24 Nov 2016
First Registration Date: 24 Nov 2016
Transfer Count: 3
Actual ARF Paid: \$55,616.00 *7188*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Nov 2026
PARF Rebate Amount: \$33,369.00

Intended COE Rebate Details

COE Expiry Date: 23 Nov 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,001.00
COE Rebate Amount: \$10,879.00
Total Rebate Amount: \$44,248.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 04 Nov 2024

OK



Land Rover Discovery Sport 2.0A
Si4 SE 7-Seater

\$64,800
Instl. \$2,156
/mth

\$18,830 /yr
31-Oct-2016
(1yr 11mths COE left)
1,999 cc
3 Owner

96,000 km



Very well maintain by only careful owner MPV with seven seater view to appreciate. Balloon scheme monthly \$1,000 plus. Wear and tears done up! STA and own workshop check welcome for your peace of mind. Flexible finance with high trade in quotes! Call or WhatsApp our sales executive to view this car and make it yours!

SG Car Choice Pte Ltd|Posted 04-Oct-2024

☐ Compare



★ StarAd View All

\$15,800. Cheaper Than Rental

\$750 Per Month. Depreciation \$8999. One Owner. Accident Free. Showroo...



**- VALUE FOR MONEY - VALUE FOR TIME
- A PEACE OF MIND**

HOTLINE: 6741 9997

[View our cars](#)

[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF C



**PRIME MOTOR
& LEASING**

**With over 200 units of vehicle
ranging from all European**

Land Rover Discovery Sport 2.0A SE Si4
7-Seater

Sold
[View](#)
[Similar](#)



30-May-2016
(1yr 6mths COE left)

N.A. 1,999 cc

3 Owners

Ideal for short term drive. Get back high body value when end of COE. Engine and gearbox still running smoothly. Just buy in peace of mind. Pre purchase inspection welcome. Well maintained exterior and interior. High trade in value, attractive bank and in house loan available, please view to believe the condition of this car and grab it while it lasts.

Universal Auto Pte Ltd|Posted 23-Aug-2024

☐ Compare

SOLD

PREMIUM AD

Land Rover Discovery Sport 2.0A Si4 SE
7-Seater

Sold
[View](#)
[Similar](#)



14-Sep-2016
(1yr 10mths COE left)

N.A. 1,999 cc

2 Owners

Posted 19-Aug-2024

☐ Compare

SOLD

Land Rover Discovery Sport Diesel
2.2A SE

Sold
[View](#)
[Similar](#)



23-Nov-2016
(2yrs COE left)

N.A. 2,179 cc 3 Owners

Diesel

Well maintained unit! Versatile and practical! \$0 downpayment, 100% loan available. Free 1 year warranty for engine & gearbox. Trade-in welcome. Viewing available 24/7 by appointments at our showroom.

☒ Warranty

Gears & Gasoline Pte Ltd|Posted 16-Aug-2024

☐ Compare

SOLD

PREMIUM AD

[Compare](#)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 30/10/2024

OWNER : NORFAEZAH BINTE HAMRAN

REG. NO. : SLX419H

MAKE/MODEL : LAND ROVER DISCOVERY

not Authorized
des
merang
4/12/25
P/P & 800/
the photo of the repair

2 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(S\$)
<u>LIST ITEMS</u>		
1	FRONT DOOR RH 11	\$ 2,890.50 X
1	REAR DOOR RH R	\$ 3,190.20 X
1	FRONT DOOR HANDLE RH 11	\$ 230.00 X
1	REAR DOOR HANDLE RH 11	\$ 230.00 X

\$	6,540.70
\$	654.07
\$	5,886.63

LESS 10%

<u>SPECIAL NETT ITEMS</u>		
1	FRONT DOOR RH STICKER WRAP 11	\$ 800.00 X
1	REAR DOOR RH STICKER WRAP 11	\$ 800.00 400 S/W
\$		1,600.00

S/N	LABOUR CHARGES	
1	To check wiring & reset headlamp focusing	\$ 11 80.00 X
2	To remove & refit door trims	\$ 11 450.00 X
3	To conduct wheel alignment	\$ 11 180.00 X
4	To apply undercoating	\$ 11 150.00 X
5	Panel Beating	\$ 800.00 200
6	To re-spray the affected areas	\$ 800.00 200

\$	2,460.00
\$	9,946.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: