

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department
Contact : 62218611 Fax No. : 62241047

Estimate : ES709683

Date : 25/10/2024
Vehicle Num. : SLW7460X
Make/Model : VOLKSWAGEN PASSAT
Chassis/Eng# : WVVZZZ3CZJE120718
Accident Date : 30/09/2024
Claim No. :
Reference :
Policy No. :

not Approved
11/11/24
L/C # 4300
Vehicle Hub
4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1PC	NETT LIST ITEMS : front bumper cur/Torn		1,244.00 ✓
2.	1PC	N/S headlamp. one	2201.50	2,574.00 ✓
3.	1PC	N/S FRONT BUMPER SIDE RETAINER 11		129.00 X
4.	1PC	N/S FRONT BUMPER SENSOR 11		346.00 X
5.	4PCS	FRONT BUMPER SENSOR O'RING 11	25.00	100.00 X
6.	4PCS	FRONT BUMPER SENSOR BRACKET 11	45.00	180.00 X
7.	1PC	FRONT BUMPER LOWER sca		606.00 ✓
8.	1PC	N/S FRONT FOG LAMP 11		611.00 X
9.	1PC	N/S WING MIRROR cur/Day		1,067.00 ✓
10.	1PC	N/S WING MIRROR COVER cur/Day	135.05	302.00 ✓
11.	1PC	N/S WING MIRROR LAMP 11		231.00 X
12.	1PC	N/S FRONT RIM 2		2,156.00 X
13.	1PC	N/S FRONT SHOCK ABSORBER 11		461.00 X
14.	1PC	N/S FRONT KNUCKLE ARM 11		896.00 X
15.	1PC	N/S FRONT WHEEL HUB 11		792.00 X
16.	1PC	N/S FRONT FENDER R		1,687.00 X
List TotalS\$:				13,382.00
10.00% Discount S\$:				1,338.20
				12,043.80
1.	1SET	SPECIAL NETT ITEMS : FRONT BUMPER CLIP 11		40.00 30

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department
Contact : 62218611 Fax No. : 62241047

Estimate : ES709683

Date : 25/10/2024
Vehicle Num. : SLW7460X
Make/Model : VOLKSWAGEN PASSAT
Chassis/Eng# : WVVZZZ3CZJE120718
Accident Date : 30/09/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	FRONT BUMPER RIVET		60.00 X
3.	1PC	N/S FRONT FENDER INNER SHIELD CLIP		40.00 X
Special Nett Total S\$:				140.00
LABOUR :				50.00 20
TO FOCUS HEADLAMP & WIRING				11 350.00 X
TO RE-CODE AND PROGRAM HEADLAMP MODULE				11 50.00 X
TO FIT SENSOR ON NEW BUMPER				11 350.00 X
TO RESET PDC				11 250.00 X
TO RUST PROOF PANELS				11 250.00 X
TO APPLY BODY SEALANT ON BODY JOINTS				11 50.00 X
TO TRANSFER AND BALANCE TYRES				11 350.00 X
TO REPLACE UNDERCARRIAGE				11 120.00 X
TO CONDUCT 4 WHEEL COMPUTERISE ALIGNMENT				\$400 000.00 450
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEEMENT				\$450 000.00 500
OF PARTS AND ALIGN THE SAME				
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA				
Labour Total S\$:				3,620.00

Repair period: should be 03 days

E. & O.E.

Total S\$: 15,803.80
=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the surveyor
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7,4881.7
102
4393.53
30
970
5393.53
22
4314