

7 Nov 2024

TP SMRT.
Hui Rong.

VSKYBAM2020146484

GBG 6981 T NISSAN NV200

No	Qty	Parts Description	Estimated Parts Price
1	1	Front headlamp -LH <i>Cracked</i>	\$ 865.00 <i>779</i>
2	1	Front headlamp top panel <i>new</i>	\$ 115.20 <i>x</i>
3	1	Front headlamp side panel	\$ 135.00 <i>x</i>
4	1	Front headlamp lower garnish <i>torn</i>	\$ 348.60 <i>✓</i>
5	1	Front grille <i>new</i>	\$ 507.10 <i>x</i>
6	1	Front grille logo <i>new</i>	\$ 75.20 <i>x</i>
7	1	Front bumper <i>torn</i>	\$ 892.00 <i>774</i>
8	1	Front bumper fog lamp <i>new</i>	\$ 320.70 <i>x</i>
9	1	Front bumper inner sponge <i>new</i>	\$ 280.70 <i>+</i>
10	1	Front bumper reinforcement	\$ 591.90 <i>+</i>
11	1	Front bumper side retainer <i>Cracked</i>	\$ 40.20 <i>✓</i>
12	1	Front fender -LH <i>Dented</i>	\$ 548.80 <i>✓</i>
13	1	Front fender inner shield <i>new</i>	\$ 127.10 <i>x</i>
			\$ 4,847.50
			\$ 484.75
			\$ 4,362.75

less 10%

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Front bumper clip (1 set) <i>new</i>	\$ 50.00 <i>✓</i>
2	1	Front fender inner shield clip (1 set) <i>new</i>	\$ 50.00 <i>x</i>
3	1	Front tyre <i>new</i>	\$ 400.00 <i>x</i>
4	1	Front wheel rim <i>new</i>	\$ 500.00 <i>x</i>
			\$ 1,000.00

Total parts : \$ 5,362.75

No	Description	Labour Charges
1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00 30
2	To conduct wheel alignment.	\$ 180.00 +
3	To apply undercoating on repaired and replaced panel.	\$ 100.00 +
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00 500 830
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00 300
Total labour :		<u>\$ 3,460.00</u>

Total parts :	\$ 5,362.75
Total labour :	\$ 3,460.00
Total repair cost :	<u>\$ 8,822.75</u>

total 3121.54

L/S: 2.5K

03 Days.

2.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: