

ESTIMATE REPORT

ATTN: MOTOR CLAIMS DEPT

VRN
MODEL

: SMQ1282C
: TOYOTA CHR

<u>PARTS REPLACEMENT</u>	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>
1 REAR DOOR LH	1	\$ 1,928.60	\$ 1,928.60
2 REAR DOOR LOWER GARNISH LH	1	\$ 290.40	\$ 290.40
3 REAR DOOR WEATHERSTRIP LH	1	\$ 210.90	\$ 210.90
4 REAR DOOR TRIM LH	1	\$ 1,852.20	\$ 1,852.20
5 REAR WINDOW LOWER MOULDING LH	1	\$ 128.40	\$ 128.40
6 REAR DOOR BLACK TAPE LH	2	\$ 53.00	\$ 106.00
7 REAR DOOR LOCK LH	1	\$ 727.30	\$ 727.30
8 REAR LH DOOR HINGE TOP	1	\$ 137.10	\$ 137.10
9 REAR LH DOOR HINGE BOTTOM	1	\$ 137.10	\$ 137.10
10 REAR FENDER LH	1	\$ 1,592.70	\$ 1,592.70
11 REAR WHEEL ARCH LH	1	\$ 203.30	\$ 203.30
12 FRONT DOOR LH	1	\$ 2,071.20	\$ 2,071.20
13 FRONT LH DOOR HINGE TOP	1	\$ 135.40	\$ 135.40
14 FRONT LH DOOR HINGE BOTTOM	1	\$ 135.40	\$ 135.40
15 FRONT DOOR BLACK TAPE LH NO.1	1	\$ 60.40	\$ 60.40
16 FRONT DOOR BLACK TAPE LH NO.2	1	\$ 30.40	\$ 30.40
17 FRONT DOOR BLACK TAPE LH NO.3	1	\$ 124.50	\$ 124.50
			\$ 9,871.30
All List -25%			\$ 2,467.83
			\$ 7,403.48
Special Nett			
1 DOOR RUBBER RIVET (SET)	1	\$ 90.00	\$ 90.00
2 DOOR TRIM CLIPS (SET)	1	\$ 90.00	\$ 90.00
			\$ 180.00
PARTS TOTAL			\$ 7,583.48

Labour Charges

1 Remove, repair and replace parts for the effected areas.	\$ 1,000.00
2 Putty, Blend And Spray Paint.	\$ 900.00
3 Remove and reinstall Door window glass to facilitate repair.	\$ 100.00
4 Dismantle and transfer Door.	\$ 360.00

No. of repair days: 6

LABOURS TOTAL

\$ 2,360.00

Grand Total	: \$	9,943.48
Add 9% GST	: \$	894.91
Nett Total	: \$	10,838.39