



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Ho Wee How (He Weihao) 1037 Serangoon Road #07-10 Singapore 328170 Mobile: 97334926
	Document No. 0	
	Document Date 13/12/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	MXPJ10R	BHXNBQ A2	27/07/2023	SNL6750A	0	34493	72/DS/SNL6750A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKBAB3601002586	M15AY491610	60	Thomas Pang W T	09/12/2024 8.00	13/12/2024 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:INDIA INTERNATIONAL PTE LTD TP VEH:GBA5368C DATE OF ACC:04.11.2024 BY:LKK-TAUFIKH @ 09.12.2024 05 WORKING DAYS				50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-LAB2 CHECK WIRING SYSTEM	BP60			134.64
4	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.	BP60			594.00
5	B	BP-WS2 REPLACE REAR TAILGATE GLASS	BP60			594.00
6	S	BP-SUBLET SUPPLY SOLAR FILM	0650			480.00
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP60			198.00
8	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR	BP60			198.00
9	B	BP-LAB2 REPLACE ACC DAMAGED PARTS	BP60			1584.00
10	B	BP-RES2 RESPRAY ACC AFFECTED AREAS	*			1312.00
11	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	0619			183.18
12	1	T52453-52902 GUARD, RR BUMPER,	1.00	766.70		766.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy



Borneo Motors

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Ho Wee How (He Weihao) 1037 Serangoon Road #07-10 Singapore 328170 Mobile: 97334926
	Document No. 0	
	Document Date 13/12/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	MXPJ10R	BHXNBQ A2	27/07/2023	SNL6750A	0	34493	72/DS/SNL6750A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKBAB3601002586	M15AY491610	60	Thomas Pang W T	09/12/2024	8.00	13/12/2024	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	2	T67005-52E03 PANEL SUB-ASSY, BACK	1.00	2175.40		2175.40
14	3	T68105-52770 GLASS SUB-ASSY, BACK	1.00	1644.20		1644.20
15	4	T64813-K2020 DAM, BACK WINDOW	1.00	28.30		28.30
16	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
17	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
18	7	T75442-52550 PLATE, BACK DOOR	1.00	56.70		56.70
19	8	T75442-52560 PLATE, LUGGAGE COMPT	1.00	56.70		56.70
20	9	T75441-52270 PLATE, LUGGAGE COMPT	1.00	63.20		63.20
21	0	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	10,693.02
	Please acknowledge receipt of vehicle	Parts 5,265.20	GST 9.00%	962.37
		Labour 4,764.64		
		Sublet 663.18		
		Lubrication/Fluid 0.00	Less	0.00
		Others 0.00	Amount Due	11,655.39

Company Copy