

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

4 days 1/5 = 3000

Owner : Pheah Wen Hui (82884366)

Accident Date : 29-Oct-24
who sh. At the day --
Yamaha

Vehicle No : FBR3508P (COE: 130520-120530)

Vehicle Model : CZD300A /
Xmax300

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fork assy	\$ 1R 980.00 X
1	Front Fork under bracket	\$ 11 398.00 X
1	Front fork upper bracket	\$ 11 280.00 X
1	Front sport rim	\$ 11 650.00 X
1	Front brake disc	\$ 11 220.00 X
1	Front rim shaft	\$ 11 75.00 X
1	Headlamp (LED)	\$ 11 1,380.00 ✓
1	Side mirror	148 \$ 11 240.00 ✓
1	Handle-bar	\$ 11 235.00 ✓
1	Handle-bar balancer set	60 \$ 11 150.00 ✓
1	Hand grip (1 set)	\$ 11 70.00 X
1	Brake levers - L/H	120 \$ 11 280.00 ✓
1	Front cowling inner panel (1 set)	\$ 11 340.00 X
1	Front cover	\$ 11 195.00 ✓
2	Footstep panels	145 \$ 11 370.00 1PC
1	Air filter cover	180 \$ 11 260.00 ✓
1	Belt cover	190 \$ 11 210.00 ✓
1	Rear footrest (1 set)	\$ 11 185.00 X
1	Main stand	\$ 11 168.00 X
1	Side stand	\$ 11 108.00 X
1	Fairing cover (1 set)	980 CR \$ 11 1,320.00 ✓
		\$ 8,114.00
	Less 10%	\$ 811.40
		\$ 7,302.60

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Pheah Wen Hui (82884366)

Accident Date : 29-Oct-24

Vehicle No : **FBR3508P** (COE: 130520-120530)

Yamaha
Vehicle Model : CZD300A /
Xmax300

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	\$ 11	38.00	X
2	Fork oils	\$ 11	50.00	X
2	Fork oil seals	\$ 11	78.00	X
1	Steering cone (1 set)	\$ 11	150.00	X
1	"X MAX" emblem	\$ nu	120.00	90
		\$	436.00	

S/No. Labour

1	To provide towing service (LOD) S\$70.00	refer to LODs	-	X
2	To check wiring and reset headlamp focusing	\$ 11	80.00	X
3	To provide labour	\$	620.00	400
4	To repair body frame	\$ 11	580.00	X
		\$	1,280.00	

Grand Total

\$ 9,018.60

Singapore Dollars: Twelve Thousand Four Hundred Thirty-Five and Cents: Sixty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p-3633
102
3269.7
90
400