

DING AUTO PTE LTD

(CARROS CENTRE)

60 JALAN LAM HUAT

#06-46/47 CARROS CENTRE

SINGAPORE 737869

ESTIMATOR: JK 8717 8218

VEHICLE NO.:	GBA8218H
MODEL:	TOYOTA DYNA 150 MANUAL
CHASSIS NO.:	JTFAT35Y803001544

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR TAILLAMP RHS / BR	1	\$ 357.10	25%	\$ 267.83	
2	REAR TAILLAMP BRACKET RHS / BT	1	\$ 61.70	25%	\$ 46.28	
3	REAR TAILLAMP LHS x nn	1	\$ 357.10	25%	\$ 267.83	
4	REAR TAILLAMP BRACKET LHS x nn	1	\$ 61.70	25%	\$ 46.28	
5	REAR END DOOR / DD	1	\$ 1,703.60	25%	\$ 1,277.70	
6	EXHUAIST x nn	1	\$ 942.30	25%	\$ 706.73	
7	REAR SPARE TYRE HOLDER ?	1	\$ 340.80	25%	\$ 255.60	
8	REAR BODY (Tailgate) x Repair	1	\$ 2,540.30	25%	\$ 1,905.23	

TOTAL:	\$ 4,773.45
--------	-------------

NO	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	REAR NUMBER PLATE WITH FRAME / BT	1	\$ 100.00	/
2	JAE COMPANY STICKER / Nec	1	\$ 400.00	300
3	REAR SPARE TYRE (Rim) / BT	2	\$ 500.00	200
4	REAR REVERSE SENSOR / Shorted	1	\$ 150.00	/
SPECIAL NETT:			\$ 500.00	

NO	LABOUR	PRICE	SURVEYOR MARKING
1	REPAIR, PANEL BEAT & SPRAY - REAR BODY, REAR PANEL, TAILGATE LATCH LHS,	\$ 1,000.00	800
2	SPRAY PAINT - REAR PANEL, REAR BODY, TAILGATE LATCH LHS,RHS	\$ 1,000.00	600
3	RUST PROOFING	\$ 80.00	30
4	ALIGN TAILLAMP AND TEST WIRING	\$ 60.00	30
TOTAL:		\$ 2,140.00	

Steve (LKK)
06/11/24, 10.30am
Without Prejudice
L/S
Resurvey After Spray
5 days

PARTS	\$ 4,773.45	
LABOUR	\$ 2,140.00	
SPECIAL NETT	\$ 500.00	
TOTAL	\$ 7,413.45	
GST 9%	\$ 667.21	
FINAL TOTAL	\$ 8,080.66	