



Autolution Industrial Pte Ltd

Tan Chong Motor Sales Pte Ltd's Authorised Dealer
19 Ubi Road 4
Singapore 408623
Tel (65) 64909666 / 67038680
Fax (65) 68467483
Business Reg. No.: 199500871W

20-August-2024

INS/SC/H/0295/24

Sompo Insurance Singapore Pte Ltd
50 Raffles Place, #03-03, S'pore Land Tower
Singapore 048623

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLR230R
POLICY NO: D23MTPV01010038

Further to our claim INS/IC/H/0222/24 we are submitting a supplementary claim for the below mentioned labor and part for the above mentioned case.

Labor charges

1	Renew intake manifold.	\$	234.00	✓
---	------------------------	----	--------	---

Replacement of Damaged Items

1	Front bumper spoiler ✓	700A	\$	380.00	S/Nett	✓
2	Bonnet hinge RH ✓	Bnt	\$	83.20	S/Nett	✓
3	Bonnet hinge LH ✓	Bnt	\$	83.20	S/Nett	✓
4	Intake manifold ✓	C1A	\$	778.50	S/Nett	✓
5	Bonnet insulator ✓	700A	\$	179.70	S/Nett	✓

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
AUTOLUTION INDUSTRIAL PTE LTD

Hamzah Sa'ad
Insurance Claim Dept

Cc: Surveyor-Mr. Marcus (LKK)



www.tanchong.com