



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24110079/Kvp3m4
300 BEACH ROAD	Date:	15/11/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGA 299S	Veh. Inspected	SJN 110Z
Policy No.	-	Coverage	0
Claim No.	24/24/24/VP05/030125	Excess	\$0.00
Assign From	CHARMAINE	Assign Date	04/11/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C180 (A)	C.C	1595
Engine No.	27491031239962	Year of Reg.	11/04/2018
Chassis No.	WDD2050402R361611	Colour	WHITE
Odometer	105524 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/35ZR19	MICHELIN	7
L/H Front Tyre	245/35ZR19	MICHELIN	7
R/H Rear Tyre	245/35ZR19	MICHELIN	7
L/H Rear Tyre	245/35ZR19	MICHELIN	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/11/2024	Inspection Date	05/11/2024
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days