

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

: SME3196T

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

: MS FIRST CAPITAL INSURANCE LIMITED

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT24002956 : 2. Nov 2024

Page

Amount

incld GST

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

#42-0116 RAFFLES QUAY HONG LEONG BUILDING

SINGAPORE 048581

: MRHFC5650JT001464

: CIVIC 1.6 VTI YM2018

: NG YEEN PENG

Description

Customer No. : WZF002 : MARSLER

Svc Advisor **Engine No**

Date

Qty

: R16B25501697

Date | Time

: 2. Nov 2024 2:13:10 PM

Surveyor Name

9% GST

Amount

Survey Date

Authorisation Date

Unit Price Disc %

Ins Policy No. **Date of Accident**

Registration No

Owner's Name

Chassis No

Model

<u>ltem</u>

.

TP DIRECT SETTLEMENT (J/NO:

OWNER: NG YEEN PENG OWNER INSURER: INCOME ACC DATE: 02/11/2024

SURVEYED BY:

	DATE:						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL						
	TP VEH: SHB5123R						
71121-TEA-T02	BASE,FR.GRILLE CHROME	1	89.20	25	66.90	6.02	72.92
71125-TEA-T01	MOLDINGFR.GRILLE	1	121.40	25	91.05	8.19	99.24
75700-TBA-A00	EMBLEM	1	18.20	25	13.65	1.23	14.88
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.28	3.43
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	39.14	474.06
71102-TBA-A10	GRILLEFR.BUMPER LOWER	1	43.80	25	32.85	2.96	35.81
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	21.80	25	16.35	1.47	17.82
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE	1	21.80	25	16.35	1.47	17.82
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.70	8.50
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.70	8.50
91505-TM8-003	CLIP,BUMPER	20	2.30	25	34.50	3.11	37.61
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	260.00	25	195.00	17.55	212.55
71130-TEA-T00	BEAM COMPFR.BUMPER	1	418.60	25	313.95	28.26	342.21
80525-TBA-A01	SENSOR ASSY,AMBIENT	4	138.20	25	103.65	9.33	112.98
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.90	25	4.42	0.40	4.82
80100-TBA-A02	CONDENSER ASSY	9	704.40	25	528.30	47.55	575.85
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	708.80	25	531.60	47.84	579.44
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	4.05	49.05
				Sum Item	2447.24	220.25	2,667.49

Printed on 4/11/2024 8:56:48 AM

This is a computer generated Invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: MS FIRST CAPITAL INSURANCE LIMITED

#42-0116 RAFFLES QUAY HONG LEONG BUILDING

Registration No

: SME3196T

Chassis No Model

Customer

: MRHFC5650JT001464 : CIVIC 1.6 VTI YM2018

Owner's Name

Ins Policy No. Date of Accident

SINGAPORE 048581

: NG YEEN PENG

Document No.

Customer No.

Date

: SQT24002956

: 2. Nov 2024

: WZF002 : MARSLER

Svc Advisor **Engine No**

: R16B25501697

Date | Time **Surveyor Name** 2. Nov 2024 2:13:10 PM

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

Page

2

Survey Date

Authorisation Date

ltem	Description	Qty	Unit Price Disc %	Amount	9% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	100.00	9.00	109.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	200.00	200.00	18.00	218.00
BC012R	PERFORM DIAGNOSTIC / SCANNING	1	450.00	450.00	40.50	490.50
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	450.00	450.00	40.50	490.50
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1950.00	1950.00	175.50	2125.50
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P)	^{3.} 1	1560.00	1560.00	140.40	1700.40
			Sum Labor	4710.00	423.90	<u>5,133.90</u>
Survey By						
Date & Time			Total Amount	7,157.24	644.15	7,801.39
Excess			Total (Inclusive of GST)			7,801.39
Status	 ;					
Signature						

Printed on 4/11/2024 8:56:48 AM

This is a computer generated Involce. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 04/11/2024 10:59 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 02/11/2024 23:50 (SGT) **Exact Location of Accident** Singapore Additional Location Information CHOA CHU KANG ST 64 BLK 642 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Honda

Vehicle Registration Number SME3196T

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner NG YEEN PENG NRIC No S7705602E Email Address ZENZOAZER@GMAIL.COM Mobile Phone No (Phone) +65-97694248 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Civic Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private hire Transmission Auto CC 1600 Vehicle Fuel First Regisration Date Chassis no Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited Policy Number / Cover Note Number 5138226066-01

DRIVER

Name of Driver LIN SWEE PENG NRIC No. S7704689E Date Of Birth 14/02/1977 Occupation Outdoor Driving Pass Date 16/05/1997 Driving License Pass Class Driving License Validity Valid Driving experience 27 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-97899557 Alt. Phone Number Email Address SWAT33@HOTMAIL.SG Address 152A BEDOK SOUTH ROAD #16-528 Address complement Postcode 461152 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Spouse Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name HENDERICK CHEONG Gender Male PASSENGER 2 Name UNKNOWN Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT

AT AROUND 11.50PM, ENTERING BLK 642 CHOA CHU KANG ST 64 BLK 642 CARPARK, THERE'S A TAXI CAR PLATE SHB5123R STOP AT THE CAR PARK GANTRY, CAR PARK GANTRY NOT WORKING, SO THE TAXI DRIVER REVERSE AND HIT MY CAR SME3196T. I WAS STATIONARY AT THAT TIME. I TRY TO HONK HIM BUT NOT SUCCESSFUL.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident

Yes Yes

TO REQUEST FROM DRIVER.

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category

Name of Driver NRIC No Contact Number

Address Address complement Postcode

Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

Insurance Company Name

SHB5123R

ANTHONY EDWARD CHEAH

S1469144H

(Phone) +65-96469878

BLK 104A CANBERRA ST #15-475

751104

VEHICLE B

WITNESS DETAILS

WITNESS 1

Name HENDERICK CHEONG Phone (Phone) +65-94568109 Email

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report some by the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Actual Filling
- 3 information provided must be as to in ut and account on possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy line by
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6 This report will be forwarded by the insolers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the ladgement of this report to the insurers, you have by donsent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

Forfourstand, acknowledge, agree and consont that

(a) My insurer, my workshop and the General insurance Association of Singapore (13LA) mayrare permitted to collect, use, disclose and/or process my personal data/personal information set out in this (four) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have assured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyors/faw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

It) processing, handing and/or dualing with my claims including the settlement of the craims and any excessory investigations relating to the craims.

- (ii) investigating the accident and/or my cigins
- (iii) carrying out and/or doaling with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about mose bring about delivery of the same as well as on the external cover of envelopeshinal packages); and/or
- (v) complying with applicable law in administering, processing, harding and/or dealing with my claims (collectively the "Purposes")
- (h) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may/are permitted to corect use disclose and/or process, my Personal information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (accluding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Perposes.

2 1523 HRS
- 02/11/2024

Possyholder's Signature / Date & Time Actual Driver

62/1/2024 1523HRS

Actual Driver's Signature (if driver is not the policy/palder) / Date & Time

Wittested by Reporting Centre Personnel (Name as in NRICKI) card)

Sketch Plan

A SME 3196T

BEAT B SHB 5123R

Ganty.

Describe Circumstance of the Accident
AT AROUND IT SOPH, ENTERING BLK 642 CHOR CHY KANG ST. 64 BLK 642 CARPARK, THERE'S A TAN CAR PLATE SHIB STOR STOP AT THE CARPARK GANTRY, CARPARK GANTRY NOT WORKING, SO THE TAXI PRIVER REVERSE AND HIT HIS CAR SHE 3196T. I WAS STATIONERS AT THAT TIME I TRY TO HOMK HIM BUT NOT CUCCESSFUL.

Declaration

If We declare the foregoing particulars are true in every respec-

July 3/11/3624 July 2/11/2024 July 2

W100002

> Back to OneMotoring

Land Transport

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

02 Nov 2024 / 14:33:30

Receipt Date/Time: 02 Nov 2024 / 14:33:30

Tax Invoice/Receipt

Receipt No.: ITNET-00000-241102-001644

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHB5123R As at 02 Nov 2024/11:50:00 Insurance Co: MS FIRST CAPITAL INSURA Insurance Enquiry - SHB5123R	ANCE LIMITED			
Enquiry Fee 20241102143152130544		25.00	2.25	27.25
	Sub-Total	25.00	2.25	27.25
	Total Before Rounding	25.00	2.25	27.25
	Rounding Difference			0.00
	Total Amount Payable			27.25
	Paid By			
	540042XXXXXX7860	eNETS Credit Card		27.25
	Total			27.25
	Cash Change			0.00
	Tendered Amount			27.25
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.