

Uax

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	03-02-25
CLAIM TYPE:	T/P CLAIM
TO:	CHINA TAIPING
VEHICLE DETAILS	
VEHICLE NO:	SNT1107Z
MAKE & MODEL:	TOYOTA ALPHARD
CHASSIS NO:	AAHH40400 6669
ACCIDENT DETAILS	
DATE:	22 January, 2025
TIME:	1855HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Defect</i>	1	\$ 3,533.20	\$ 3,533.20
2	TAIL GATE LOGO <i>2pc</i>	1	\$ 95.00	\$ 95.00
3	TAIL GATE ALPHARD EMBLEM <i>1pc</i>	1	\$ 110.00	\$ 110.00
4	TAIL GATE DAMPER <i>2pc</i>	2	\$ 280.00	\$ 560.00
5	TAIL GATE HINGE <i>2pc</i>	2	\$ 95.00	\$ 190.00
6	TAIL GATE LAMP <i>2H each</i>	2	\$ 3,350.20	\$ 6,700.40
7	TAIL GATE INNER TRIM BOARD <i>Defect</i>	1	\$ 1,155.20	\$ 1,155.20
8	TAIL GATE INNER HANDLE <i>new</i>	1	\$ 98.00	\$ 98.00
9	TAIL GATE LOCK <i>Defect</i>	1	\$ 620.00	\$ 620.00
10	TAIL GATE WEATHERSTRIP <i>new</i>	1	\$ 350.00	\$ 350.00
11	TAIL GATE ANTENNA SWITCH <i>each</i>	1	\$ 180.00	\$ 180.00
12	TAIL GATE OUTER LOWER GARNISH <i>new Defect</i>	1	\$ 520.00	\$ 520.00
13	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 250.00	\$ 250.00
14	REAR BUMPER <i>Defect</i>	1	\$ 1,055.30	\$ 1,055.30
15	REAR BUMPER TOWING COVER <i>new</i>	2	\$ 80.00	\$ 160.00
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 110.00	\$ 220.00
17	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 150.00	\$ 300.00
18	REAR BUMPER SENSOR <i>Defect 2 pieces</i>	4	\$ 320.00	\$ 1,280.00
19	REAR QUARTER BUMPER <i>Not new</i>	2	\$ 350.00	\$ 700.00
20	REAR QUARTER BUMPER SIDE RETAINER <i>new</i>	2	\$ 130.00	\$ 260.00
21	REAR FENDER INNER TRIM <i>new</i>	2	\$ 1,355.60	\$ 2,711.20

2840

990

885

510

640

X
X
X

22	REAR END PANEL <i>Dented</i>	1	\$ 2,092.50	\$ 2,092.50
23	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 250.00	\$ 250.00

1290

89620.30
67215.22

TOTAL PRICE \$ 23,390.80
LESS 25% \$ 5,847.70
SUB TOTAL PRICE \$ 17,543.10

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	TAILGATE OUTER LOWER GARNISH CLIPS (SET) <i>new</i>	1	\$ 300.00	\$ 300.00
4	TAILGATE WINDSCREEN SEALANT <i>New</i>	1	\$ 100.00	\$ 100.00
5	REAR BUMPER CLIPS SET <i>New</i>	1	\$ 20.00	\$ 20.00
6	REAR FENDER INNER TRIM CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL SEALANT <i>New</i>	1	\$ 120.00	\$ 120.00
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
11	CAR WRAP <i>New</i>	1	\$ 1,250.00	\$ 1,250.00
			TOTAL	\$ 1,900.00

+
✓
70
60
✓
+
60
✓
1100

1300

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,000.00	\$ 2,000.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,000.00	\$ 2,000.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00
6	TO REMOVE AND REFIX TAILGATE MECHANISM	1	\$ 180.00	\$ 180.00
7	TO REMOVE AND REFIT REVERSE SENSOR AND SETTING	1	\$ 100.00	\$ 100.00
8	TO REMOVE AND REFIX REVERSE CAMERA AND SETTING	1	\$ 100.00	\$ 100.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 120.00	\$ 120.00

800
600
80
30
60
60
50
50
✓

TOTAL \$ 5,060.00

1850

ESTIMATE REPORT

TOTAL PARTS COST	\$	19,443.10
TOTAL LABOUR COST	\$	5,060.00
TOTAL REPAIR COST	\$	24,503.10

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM
NO. OF DAYS

Adnan Lj
1/2 03/02/25

07 Days

total: 910365.22

1/2 8.3K

8.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PRECISION
CORPORATION

PRECISION WRAP PTE LTD (201911856R)
68 KAKI BUKIT AVE6 #01-03 ARK@KB
SINGAPORE 417896

QUOTATION

No. : QT-2025020301

SNT 1107 Z

TOYOTA ALPHARD

Attn: NATALIE

TEL : +65 9338 6968

Your Ref. : Dson

From :

C. C. :

Date : 3 FEB 2025

Page : 1 of 1

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Total S\$
1.	To Supply Vinyl Wrap & Provide Labour For Installation (REAR BOOT & REAR BUMPER) MATERIAL: CUSTOM WRAP PREMIUM PRINT	1	1,100.00	1,100.00

Validity : 30 Days

Delivery Term :

Payment Term : 50% Deposit Require Upon Quotation Confirm

Total 1,100.00

Note : Prices are subjected to change without prior notice. We hope that our quotation is favourable to you and looking forward to receive your valued orders in due course. Thank and regards.

Yours faithfully,

Administrator