



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110112/Uqp3e2
75 BRAS BASAH ROAD	Date:	12/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 9875M	Veh. Inspected	SLA 8607A
Policy No.	-	Coverage	0
Claim No.	MT/1302160-002	Excess	\$0.00
Assign From	CHRYLLIS QUAH	Assign Date	06/11/2024

2. Vehicle Details

Make & Model	HYUNDAI ELANTRA	C.C	1591
Engine No.	G4FGGU118168	Year of Reg.	21/03/2016
Chassis No.	KMHD841CMHU099778	Colour	SILVER
Odometer	398494 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55ZR16	ARIVO	6
L/H Front Tyre	205/55ZR16	ARIVO	6
R/H Rear Tyre	205/55ZR16	ARIVO	6
L/H Rear Tyre	205/55ZR16	ARIVO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2024	Inspection Date	07/11/2024 (10:44)
Survey held at	8 KAKI BUKIT AVENUE 4 #04-35 PREMIER @ KAKI BUKIT SINGAPORE 415875 - REPAIRER: GALAXY AUTO CARE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days