



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110113/Uvh3m4
75 BRAS BASAH ROAD	Date:	12/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMS 7866T	Veh. Inspected	SBT 3280J
Policy No.	-	Coverage	0
Claim No.	MT/1302225-002	Excess	\$0.00
Assign From	MARCUS	Assign Date	06/11/2024

2. Vehicle Details

Make & Model	HONDA CIVIC 1.6L VTIS AT	C.C	1598
Engine No.	R16B21100591	Year of Reg.	27/11/2014
Chassis No.	MRHFB1630DP090005	Colour	GREY
Odometer	236990 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	YOKOHAMA	5
L/H Front Tyre	205/55R16	YOKOHAMA	5
R/H Rear Tyre	205/55R16	YOKOHAMA	5
L/H Rear Tyre	205/55R16	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/10/2024	Inspection Date	06/11/2024 (16:36)
Survey held at	HONG AUTO SERVICES 2 KAKI BUKIT AVENUE 2 #01-28 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.