



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. : SAC2401318

INV Date : 11-11-2024

Reference CS3/III24110120/Rnp3m4

Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 4342C
Insured Veh. GBE 3550J
Claim No. MFL2024D0013210
Policy No. D23MFL0003699_01
Accident Date 02/11/2024
Inspection Date 06/11/2024

Description	Amount
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	170.00
- First Inspection 06.11.2024 12.05pm	0.00
Merimen Fee	12.00
Sub-Total	182.00
GST (9%)	16.38
Grand Total	198.38

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML
