

CARSMITH PRIVATE LIMITED
PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875
 Tel: 9091 0000/ Email: claims@carsmith.biz

Not Authorized
 in
 Moray
 7/11/24
 d/s \$ 4000
 take photo after repair
 4 days

VEHICLE NO: GBF968C
 MAKE & MODEL: TOYOTA HIACE
 DOA: 04.11.2024
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 1,890.00	DD/3ent ✓
TAILGATE RUBBER TOP GARNISH	1	\$ 102.70	SC X
TAILGATE RUBBER	1	\$ 328.50	SC X
TAILGATE LOCK	1	\$ 285.10	SC X
TAILGATE HINGE	2	\$ 190.50	17 X
TAILGATE ABSORBER	2	\$ 590.00	17 X
TAILGATE CENTER GARNISH	1	\$ 186.50	17 X
TAILGATE INNER BOARD	1	\$ 335.20	17 X
TAILGATE LOCK ACTUATOR	1	\$ 430.60	17 X
TAILGATE EMBLEM LOGO	1	\$ 108.00	neu ✓ 85.10
TAILGATE WINDSCREEN MOULDING	1	\$ 218.50	NS X
TAILGATE WINDSCREEN	1	\$ 1,250.00	17 X
TAILGATE STOPPER	2	\$ 80.00	17 X
REAR END PANEL INNER	1	\$ 912.70	R X
REAR END PANEL OUTER	1	\$ 486.50	DD/3ent ✓
REAR FLOOR BOARD PANEL	1	\$ 2,381.40	17 X
REAR BUMPER	1	\$ 698.00	De/Ten ✓
REAR BUMPER SIDE RETAINER	2	\$ 161.60	MS cre 1PC 80.90
REAR BUMPER LOWER SUPPORT BRACKET	4	\$ 244.80	SC X
REAR TAILLAMP RH	1	\$ 382.20	17 X
REAR TAILLAMP GARNISH RH	1	\$ 159.50	17 X
REAR TAILLAMP PANEL RH	1	\$ 322.70	17 X
RAR TAILLAMP BRACKET RH	1	\$ 118.00	17 X
REAR TAILLAMP LH	1	\$ 382.20	CN ✓
REAR TAILLAMP GARNISH LH	1	\$ 159.50	TW ✓
REAR TAILLAMP PANEL LH	1	\$ 322.70	DD/3ent ✓
RAR TAILLAMP BRACKET LH	1	\$ 118.00	17 X
REAR LOWER CROSS MEMEBR	1	\$ 351.00	17 X
REAR TAILLAMP LOWER GARNISH RETAINER	1	\$ 81.00	17 X
REAR FENDER LH	1	\$ 2,745.00	R X
REAR DOOR RAILING LH	1	\$ 368.00	17 X
		\$ 16,390.40	
	LESS 25%	\$ 1,639.04	
	SUB TOTAL	\$ 14,751.36	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	neu 30 S/N
REAR NUMBER PLATE	1 SET	\$ 80.00	17 X
TAILGATE STICKER '70KM/H'	1	\$ 45.00	neu 10 S/N
REVERSE SENSOR	1 SET	\$ 480.00	SC X
REVERSE CAMERA	1 SET	\$ 480.00	17 X
JOINT SEALANT <i>Rear wind screen</i>	1	\$ 120.00	40 S/N
	SUB TOTAL	\$ 1,255.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20

REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	12X
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	800
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,600.00	950
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	50
SUB TOTAL		\$ 4,020.00	
GRAND TOTAL		\$ 20,026.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4104.90
252
3078.68
80
1850
3078.68
202
4000.