

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/FC/24110122/UV3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBF968C

at Workshop m/s

CorSmith

of

Insured:

SHB44627

Policy No.

Claims No. D24009732MFCT


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

\$22k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C703h

Date:

Person Contacted:

Vehicle: IN / OUT

ATA 8419

Veh No:

GBF968C

Yr Regn:

23/06/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C.

2982

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

385-363T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P500199719Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxamila

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/11/24

D.O.I.

7/11/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/11/242/5 \$4000Dep 14th informed Alex

(red 16,026.36, 80%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	703H
Vehicle Details	
Vehicle No.:	GBF968C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2626759
Chassis No.:	JTFHT02P500199719
Maximum Power Output:	-
Open Market Value:	\$27,741.00
Original Registration Date:	23 Jun 2016
First Registration Date:	23 Jun 2016
Transfer Count:	3
Actual ARF Paid:	\$1,388.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,434.00
COE Rebate Amount:	\$8,419.00
Total Rebate Amount:	\$8,419.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 07 Nov 2024

OK



PREMIUM AD

Toyota Hiace Commuter

\$30,500

3.0A GL

Instl. \$1,791

/mth



1 Owner Diesel

22-Apr-2016

(1yr 5mths COE left)



N.Air 2,982 cc



Pristine condition! 1 owner only! Full service and all wear and tear parts done by reputable in-house workshop! 100% loan available from 2.48% per annum! 1 to 1 exchange without cash top up! Hurry and call our friendly sales adviser for more information before it's sold! Best price guaranteed!

First Motoring|Posted 01-Nov-2024

☐ Compare


PREMIUM AD

Toyota Hiace

\$35,800

3.0A

Instl. \$1,784

/mth



Diesel

20-Jul-2016

(1yr 8mths COE left)



N.Air 2,982 cc

2 Owners



Toyota Hiace diesel with auto transmission.

Skylink Auto Pte Ltd|Posted 01-Nov-2024

☐ Compare


★ StarAd | View All

2023 Toyota Alphard 2.5 S C-Package

One owner only, low mileage and in excellent condition 88 Auto Pte Ltd



Think One Automobile



NEW & USED COMMERCIAL VEHICLES



PREMIUM AD

Toyota Hiace

~~\$23,500~~

3.0M

Instl. \$1,302

/mth



2 Owners Diesel

10-May-2016

(1yr 6mths COE left)



129,429 km 2,982 cc



Well-kept and, maintained in good condition. No repairs needed. Manual transmission, Diesel engine. Suitable for short term use. Kindly do call us for a viewing appointment.

Think One Automobile & Trading|Posted 01-Nov-2024

☐ Compare


PREMIUM AD


Toyota Hiace Commuter

\$32,800

3.0A GL

Instl. \$2,351

/mth



5 Owners Diesel

18-Jan-2016

(1yr 2mths COE left)



N.Air 2,982 cc



MORE THAN 5 UNITS AVAILABLE TO CHOOSE FROM! NEW OPTIONS AVAILABLE AS WELL! COE CAN BE FURTHER EXTENDED FOR ANOTHER 5 + 5 OR 10 YEARS! HIGH SPECS GL KEYLESS ENTRY MODEL! PREMIUM 3 MONTHS WARRANTY WITH FURTHER LUCRATIVE PACKAGES! Flexible Financing Packages, High Loan Options Welcome. Ready For Immediate Handover. Whatsapp/Call Our Friendly Sales Consultant Listed Below To View This Beauty Today!

Car (S) Pte Ltd|Posted 01-Nov-2024

☐ Compare

[Compare](#)

CARSMITH PRIVATE LIMITED
PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875
Tel: 9091 0000/ Email: claims@carsmith.biz

Not Authorized
 Mr. Moray
 7/11/24
 d/s \$4000
 take place after repair
 4 days

VEHICLE NO: GBF968C
 MAKE & MODEL: TOYOTA HIACE
 DOA: 04.11.2024
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 1,890.00	DD/Int ✓
TAILGATE RUBBER TOP GARNISH	1	\$ 102.70	SCX
TAILGATE RUBBER	1	\$ 328.50	SCX
TAILGATE LOCK	1	\$ 285.10	SCX
TAILGATE HINGE	2	\$ 190.50	17 X
TAILGATE ABSORBER	2	\$ 590.00	17 X
TAILGATE CENTER GARNISH	1	\$ 186.50	17 X
TAILGATE INNER BOARD	1	\$ 335.20	17 X
TAILGATE LOCK ACTUATOR	1	\$ 430.60	17 X
TAILGATE EMBLEM LOGO	1	\$ 108.00	17 ✓ 85.10
TAILGATE WINDSCREEN MOULDING	1	\$ 218.50	NS X
TAILGATE WINDSCREEN	1	\$ 1,250.00	17 X
TAILGATE STOPPER	2	\$ 80.00	17 X
REAR END PANEL INNER	1	\$ 912.70	R X
REAR END PANEL OUTER	1	\$ 486.50	DD/Int ✓
REAR FLOOR BOARD PANEL	1	\$ 2,381.40	17 X
REAR BUMPER	1	\$ 698.00	DD/Int ✓
REAR BUMPER SIDE RETAINER	2	\$ 161.60	MS cro 1PC 80.90
REAR BUMPER LOWER SUPPORT BRACKET	4	\$ 244.80	SCX
REAR TAILLAMP RH	1	\$ 382.20	17 X
REAR TAILLAMP GARNISH RH	1	\$ 159.50	17 X
REAR TAILLAMP PANEL RH	1	\$ 322.70	17 X
REAR TAILLAMP BRACKET RH	1	\$ 118.00	17 X
REAR TAILLAMP LH	1	\$ 382.20	CR ✓
REAR TAILLAMP GARNISH LH	1	\$ 159.50	TM ✓
REAR TAILLAMP PANEL LH	1	\$ 322.70	DD/Int ✓
REAR TAILLAMP BRACKET LH	1	\$ 118.00	17 X
REAR LOWER CROSS MEMEBR	1	\$ 351.00	17 X
REAR TAILLAMP LOWER GARNISH RETAINER	1	\$ 81.00	17 X
REAR FENDER LH	1	\$ 2,745.00	R X
REAR DOOR RAILING LH	1	\$ 368.00	17 X
		\$ 16,390.40	
	LESS 25%	\$ 1,639.04	
	SUB TOTAL	\$ 14,751.36	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	17 30 S/N
REAR NUMBER PLATE	1 SET	\$ 80.00	17 X
TAILGATE STICKER '70KM/H'	1	\$ 45.00	17 10 S/N
REVERSE SENSOR	1 SET	\$ 480.00	SCX
REVERSE CAMERA	1 SET	\$ 480.00	17 X
REAR SEALANT Rear windscreen	1	\$ 120.00	40 S/N
	SUB TOTAL	\$ 1,255.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20

REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	12X
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	800
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,600.00	950
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	50
SUB TOTAL		\$ 4,020.00	
GRAND TOTAL		\$ 20,026.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4104.90
 252
 3078.68
 80
 1850
 5008.68
 202
 4000.