

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Chan Ka Keong (90676370)

Accident Date : 17-Sep-24

Vehicle No : JVH4615 (DOR: 31052022)

Vehicle Model : Modenas/Kriss MJ110H

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy	\$ 960.00X
1	Fork under bracket	\$ 260.00X
1	Front rim	\$ 480.00X
1	Front brake disc	\$ 285.00X
1	Front rim shaft	\$ 88.00X
1	Front rim bearing	\$ 90.00X
1	Handle bar	\$ 255.00✓
1	Handle bar end	\$ 88.00✓
1	Hand grip (1 set)	\$ 76.00✓
1	Meter assy	\$ 455.00X
1	Meter cover	\$ 135.00✓
1	Headlamp assy	\$ 485.00X
1	Brake lever	\$ 95.00✓
1	Front signals	\$ 185.00X
1	Side mirror (1 set)	\$ 128.00✓
1	Fairing assy (1 set)	\$ 735.00✓
1	Front footrest bracket	\$ 225.00✓
1	Front footrest rubber	\$ 95.00✓
1	Basket	\$ 125.00✓
1	Brake pedal	\$ 165.00✓
1	Exhaust assy	\$ 680.00X
1	Exhaust protector	\$ 165.00✓
1	Rear footrest (1 set)	\$ 125.00X
1	Rear footrest bracket (1 set)	\$ 325.00X
		\$ 6,705.00
	Less 10%	\$ 670.50
		\$ 6,034.50

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Chan Ka Keong (90676370)

Accident Date : 17-Sep-24

Vehicle No : JVH4615 (DOR: 31052022)

Vehicle Model : Modenas/Kriss
MJ110H

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	\$ net	38.00	105/2
2	Fork oils	\$ 11	30.00	X
2	Fork oil seals	\$ 11	56.00	X
1	Steering cone (1 set)	\$ 11	96.00	X
1	Rear box	\$ net	480.00	280
1	Rear box bracket	\$ but	180.00	110
1	Sticker	\$ net	120.00	60
		\$	1,000.00	

S/No.

Labour

1	To provide towing service(LOD) S\$80.00	refer to LOD	\$	-	X
2	To check wiring and reset headlamp focusing		\$ 11	80.00	X
3	To repair body frame		\$ 11	420.00	X
4	To provide labour		\$	450.00	300
			\$	950.00	

Grand Total

\$ 7,984.50

Singapore Dollars: Seven Thousand Nine Hundred Eighty-Four and Cents: Fifty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1832
02
1648.80
460
300
2408.8