

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : S Karunanithi (84281462)

Accident Date : 04-Nov-24

Vehicle No : FBU207L (COE: 190722-18073)

Vehicle Model : Honda Vario 160
CVT

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy	\$ Suc 1,080.00 X
1	Front rim shaft	\$ n 128.00 X
2	Front side cover (matt)	\$ cut 220.00 /
1	Headlamp (LED)	\$ Cu 1,080.00 /
1	Side mirror	110 \$ Cu 180.00 /
1	Handle bar	\$ su 265.00 X
1	Handle bar balancer - 1 set	60 \$ Cu 140.00 /
1	Hand grip - 1 set	\$ n 90.00 X
1	Brake lever - (1 set)	90 \$ Cu 220.00 /
1	Fairing assy	\$ Cu 950.00 /
2	Footstep panel	160 0/5 \$ Cu 380.00 1P C
2	Footstep lower cover	145 0/5 \$ Cu 450.00 1P C
1	Rear mudguard	110 \$ Great 310.00 /
1	Exhaust assy	\$ R 850.00 X
1	Exhaust protector	\$ Cu 165.00 /
1	Exhaust end cap	60 \$ Cu 135.00 /
		\$ 6,643.00
Less 10%		\$ 664.30
		\$ 5,978.70

Special Net Items

1	Rear Number plate (1 set)	\$ sca 38.00 20 S/N
2	Fork oils	\$ n 30.00 X
2	Fork oil seal	\$ n 56.00 X
1	Steering ccone (1 set)	\$ n 120.00 X
1	Rear box	\$ Cu 480.00 300
1	Rear box bracket	\$ Bent 180.00 100
		\$ 904.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : S Karunanithi (84281462)

Accident Date : 04-Nov-24


Vehicle No : FBU207L (COE: 190722-18073

Vehicle Model : Honda Vario 160
CVT

Estimated Repair Costs

S/No.	Labour			
1	To provide towing service (LOD)	Refer to LOD	\$ -	X
2	To check wiring and reset headlamp focussing		\$ 17 80.00	X
3	To repair body frame		\$ 17 450.00	X
4	To provide labour		\$ 480.00	300
			\$ 1,010.00	
Grand Total			\$ 7,892.70	

Singapore Dollars: Seven Thousand Eight Hundred Ninety-Two and Cents: Seventy only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3150
112
2835
420
300
3555
112
2844