



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110138/Uqh3e2
75 BRAS BASAH ROAD	Date:	06/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBQ 7102E	Veh. Inspected	FBU 207L
Policy No.	-	Coverage	0
Claim No.	MT/1303008-001	Excess	\$0.00
Assign From	MARCUS	Assign Date	07/11/2024

2. Vehicle Details

Make & Model	HONDA VARIO 160	C.C	157
Engine No.	KFA1E1049569	Year of Reg.	19/07/2022
Chassis No.	MH1KFA119NK049479	Colour	BLACK
Odometer	93111 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110-70-14	MAXXIS	6
L/H Front Tyre			
R/H Rear Tyre	120-70-14	MAXXIS	6
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/11/2024	Inspection Date	08/11/2024 (14:27)
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days