

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0847/2024/KS
DATE : 8-Nov-24
WIP : 37538

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/11/2024

YOUR INSURED VEH NO : SLM 2112 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR GANJU AMIT
ADDRESS : 53B GRANGE ROAD
#20-02, SPRING GROVE
SINGAPORE 249567
TELEPHONE : HP +65 98538689
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7220151734
VEHICLE NO : SMJ 3930 P
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 28/12/2022
ENGINE NO : DKY 015975
CHASSIS NO : WAUZZZF26MN098452
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Nov-24
PLACE OF ACCIDENT : NEAR BUS STOP POLE 03031 (RAFFLES PLACE STATION EXIT)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3930 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00 ✓	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT.	S/N \$	280.00 ✓	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00 1000	
4	TO RESPRAY REAR BUMPER AND REAR LID.	\$	2,200.00 1100	
5	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS.	S/N \$	800.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 6,332.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3930 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER / 011	1	\$	3,397.00
2	REAR BUMPER FIXING PARTS X	1	\$	262.00
3	REAR BUMPER SPOILER - DARK CHROME MATT X	1	\$	1,107.00
4	REAR BUMPER TRIM - LH / RH X	2	\$	614.00
5	REAR BUMPER TRIM - CENTER X	1	\$	215.00
6	REAR BUMPER SECURING STRIP X	1	\$	216.00
7	REAR LIGHT REFLECTOR - LH / RH OUTER X	2	\$	98.00
8	REAR LIGHT REFLECTOR - LH / RH INNER X	2	\$	82.00
9	REAR BUMPER REINFORCEMENT BEAM X	1	\$	1,232.00
10	REAR BUMPER REINFORCEMENT BEAM SEAL - LH / RH X	2	\$	18.00
11	REAR BUMPER GUIDE PROFILE - LH / RH X	2	\$	168.00
12	REAR BUMPER GUIDE SECTION - LH / RH UPPER X	1	\$	114.00
13	REAR BUMPER HOLDING STRAP - CENTER X	1	\$	149.00
14	REAR LID X	1	\$	4,960.00
15	REAR LID PACKING ADHESIVE X	1	\$	23.00
16	REAR LID ATTACHMENT PARTS X	1	\$	199.00
17	REAR LID LOCK COVER X	1	\$	9.00
18	REAR LID LOCK ?	1	\$	323.00
19	AUDI EMBLEM / MC	1	\$	162.00
20	"A6" EMBLEM / MC	1	\$	116.00
21	REAR LID CHROME STRIP - CENTER / MC	1	\$	435.00
22	SUNDRIES ?		\$	500.00
TOTAL SPARE PARTS		:	\$	14,399.00
TOTAL LABOUR CHARGES		:	\$	6,332.00
GRAND TOTAL		:	\$	20,731.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

5ter CLKK/
18/11/24, 19.3004

W R
PIP

by BLN, 5 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT