



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Ref: Date: Code:	CS/INC24110152/Uvh3m4 16/12/2024 INC
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNH 5477S	Veh. Inspected	VDH 4259
	Policy No.	-	Coverage	0
	Claim No.	MT/1302859-002	Excess	\$0.00
	Assign From	MARCUS	Assign Date	07/11/2024
2. Vehicle Details				
	Make & Model	YAMAHA Y15ZR	C.C	150
	Engine No.	G3D3E-265097	Year of Reg.	19/06/2019
	Chassis No.	PMYUG0520K0021077	Colour	RED
	Odometer	85938 KM	Steering	AFFECTED
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	70-90-17	MAXXIS	6
	L/H Front Tyre			
	R/H Rear Tyre	70-90-17	MAXXIS	6
	L/H Rear Tyre			
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	05/11/2024	Inspection Date	08/11/2024 (10:05)
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				