

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Not Authorised  
N/A  
8/11/24

4 days 2/s \$1800

Name : Hanafi Bin Musa (82508874) 4/s \$1800

Accident Date : 05-Nov-24

Like the Attorney

Vehicle No : VDH4259 (DOR: 19062019)

Vehicle Model : Yamaha Y15ZR

## Estimated Repair Costs

| Qty               | Description                | Amount S(\$)            |
|-------------------|----------------------------|-------------------------|
| <u>List Items</u> |                            |                         |
| 2                 | Front fork tube assy       | 520 \$ Bent/tm 640.00 ✓ |
| 1                 | Fork under bracket         | 160 \$ Bent 185.00 ✓    |
| 1                 | Handle-bar                 | \$ 11 105.00 X          |
| 1                 | Hand grip (1 set)          | \$ 11 55.00 X           |
| 1                 | Handle bar ends            | \$ 11 78.00 X           |
| 2                 | Side mirrors               | \$ 11 110.00 X          |
| 1                 | Front pilot light          | \$ 11 228.00 X          |
| 2                 | Front signals              | \$ 11 140.00 X          |
| 1                 | Front signal lower garnish | \$ CNA 95.00 ✓          |
| 1                 | Front fender               | 110 \$ cre 180.00 ✓     |
| 1                 | Fairing assy (1 set)       | 528 \$ cre 625.00 ✓     |
| 1                 | Front rim                  | 380 \$ warped 528.00 ✓  |
| 1                 | Exhaust protector          | \$ 11 60.00 X           |
| 1                 | Exhaust protector end cap  | \$ 11 45.00 X           |
| 1                 | Rear fender - 1            | \$ Dis 95.00 ✓          |
| 1                 | Rear fender - 2            | \$ Dis 68.00 ✓          |
| 1                 | Rear fender bracket        | \$ tm 106.00 ✓          |
| 1                 | Rear signal                | \$ 11 180.00 X          |
| 1                 | Rear number plate lamp     | \$ Bro 98.00 ✓          |
| 1                 | Rear Rim                   | \$ Bent 350.00 ✓        |
| 1                 | Rear rim shaft             | \$ Su 98.00 X           |
| 1                 | Swing arm                  | \$ Bent/tm 380.00 ✓     |
| 1                 | Swing arm bush             | 100 \$ nec 180.00 ✓     |
| 1                 | Swing arm shaft            | \$ su 98.00 X           |
|                   |                            | \$ 4,727.00             |
| Less 10%          |                            | \$ 472.70               |
|                   |                            | \$ 4,254.30             |

## Special Nett Items

|   |                           |                  |
|---|---------------------------|------------------|
| 1 | Rear Number plate (1 set) | \$ Bent 38.00 20 |
| 2 | Fork oils                 | \$ 11 30.00 X    |
| 2 | Fork oil seals            | \$ 11 56.00 X    |
| 1 | Steering cone (1 set)     | \$ nec 95.00 60  |
| 1 | Sticker (1 set)           | \$ nec 95.00 80  |
|   |                           | \$ 314.00        |

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Hanafi Bin Musa (82508874)

Accident Date : 05-Nov-24

Vehicle No : VDH4259 (DOR: 19062019)

Vehicle Model : Yamaha Y15ZR

## Estimated Repair Costs

| <u>S/No.</u> | <u>Labour</u>                               |              |    |             |
|--------------|---------------------------------------------|--------------|----|-------------|
| 1            | To provide towing service (LOD) S\$40.00    | refer to LOD | \$ | - X         |
| 2            | To check wiring and reset headlamp focusing |              | \$ | 1^ 80.00 X  |
| 3            | To realign body frame                       |              | \$ | 1^ 420.00 X |
| 4            | To provide labour                           |              | \$ | 480.00 300  |
|              |                                             |              | \$ | 980.00      |
| Grand Total  |                                             |              | \$ | 5,548.30    |

Singapore Dollars: Five Thousand Five Hundred Forty-Eight and Cents: Thirty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-2990  
107  
2694.00  
160  
300  
3151