



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110153/Uvp3m4
16 RAFFLES QUAY	Date:	15/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3743J	Veh. Inspected	SND 5580Y
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009767MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	07/11/2024

2. Vehicle Details

Make & Model	TOYOTA ALPHARD HYBRID ELEGANCE (AUTO)	C.C	2494
Engine No.	2AR2739776	Year of Reg.	11/01/2022
Chassis No.	JTNHS3DH308060818	Colour	BLACK
Odometer	152095 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60R17	TRANSFORCE	7
L/H Front Tyre	225/60R17	TRANSFORCE	7
R/H Rear Tyre	225/60R17	TRANSFORCE	7
L/H Rear Tyre	225/60R17	TRANSFORCE	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/11/2024	Inspection Date	07/11/2024
Survey held at	53 UBI AVENUE 1 #01-23, SINGAPORE 408934 – REPAIRER: MERIBEL AUTO PTE LTD		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days