

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

MSIG INSURANCE (SINGAPORE) PTE.LTD

4 SHENTON WAY

#21-01 SGX CENTRE 2

SINGAPORE 068807

SKZ1541G

Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

VEHICLE NO : SMF3950C
MAKE/MODEL : HYUNDAI ELANTR
ACC DATE : 29.10.2024

PARTICULAR

QTY

LIST PRICE

		UNIT PRICE		AMOUNT
		SS		SS
1	1 REAR BOOTLID	1,783.00	R	1,783.00 X
2	1 REAR BOOT LOGO	58.80	SC	58.80 X
3	1 REAR BOOT EMBLEM 'ELANTRA'	68.80	SC	68.80
4	1 REAR BOOT EMBLEM 'S'	62.40	SC	62.40
5	1 REAR BOOT INNER LOCK	230.60	SC	230.60 X
6	2 REAR BOOT LAMPS -R/L	441.50	11	883.00 X
7	1 REAR BOOT W/STRIP	241.20	SC	241.20 X
8	1 REAR BUMPER	671.60	DD/20.11	671.60
9	1 REAR BUMPER DIFUSSER	361.60	SC	361.60
10	2 REAR BUMPER RELECTOR -R/L	110.20	11	220.40 X
11	1 REAR BUMPER REINFORCMENT	481.50	DIS	481.50
12	1 REAR BUMPER SIDE RETAINERS -R/L	65.50	SC	65.50
13	1 REAR END PANEL	520.60	R	520.60 X
14	1 REAR END PANEL GARNISH	161.20	11	161.20 X
15	1 REAR TAILLAMP -LH	651.20	11	651.20 X
				6,461.40
		LESS 20%		1,292.28
				5,169.12

SPECIAL NETT ITEMS

1	1 (SET) REAR BOOT INNER TRIM CLIP	50.00	11	50.00 X
2	1 (SET) REAR BUMPER CLIP	50.00	SC	50.00 30
3	1 (SET) REAR REVERSE SENSOR	280.00	no broken	280.00 200
				380.00

LABOUR CHARGES :

1	TO CHECK REAR ELECTRICAL WIRING	50.00	20
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	120.00	X
3	TO REMOVE AND REPLACE REVERSE SENSORS	60.00	30
4	TO TUFF KOTE	80.00	X
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,080.00	700
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	900.00	500
	Total :	2,290.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 7,839.12

7/11/24
22
511.28
230

not allowed
in
new
7/11/24
d/s & 2000
the first time

4 days