

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

ECICS  
25 OCT 2024

Estimate No. : b1 71609  
Date Estimated : 25/10/2024  
Prepared By : Chua Kee Sin

Page No. : 1 of 5

**- ESTIMATE REPAIR FOR -**

Tan Wei Cheong  
31 Amber Gardens  
#06-03

Singapore 439967

**- ACCOUNT - 40000**

Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SGV5219E  | WBAJA12010BJ21240 | 04/07/2019 | 520i  | 93822   |

**DESCRIPTION****VALUE**

Replace rear bumper include remove attachment etc and carryout necessary re pairing work on accident damage area

850 1,275.00

Painting rear bumper

✓ 1,038.00

To check electrical wiring system and lighting at the rear section for proper function.

✓ 177.00

Sundries.

80 150.00

Total Labour 1: 2,640.00

**DESCRIPTION****QTY****PRIC****VALUE**

(S/L) LH PROTECTION FOIL

1

14.70

xnn 14.70

(S/L) RH PROTECTION FOIL

1

14.70

xnn 14.70

REAR BUMPER CARRIER

1

633.60

nn X 633.60

REAR BUMPER LH SIDE GUIDE

1

203.40

cra 203.40

REAR BUMPER TRIM STRIP

1

82.20

cut 82.20

REAR BUMPER TOWING EYE FLAP PRIMED

1

57.50

nn X 57.50

REAR BUMPER PANEL PRIMED (PDC/PMA)

1

1,731.95

de 1,731.95

REAR LH REAR REFLECTOR

1

45.70

cra 45.70

DECOUPING RING PDC TORQUE CONVERTER

6

5.65

nn 33.90

ULTRASONIC SENSOR IMPERIALBLAU(WA89

1

391.40

an 2,348.40

Total Parts : 5,166.05

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 71609  
Date Estimated : 25/10/2024  
Prepared By : Chua Kee Sin

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SGV5219E  | WBAJA12010BJ21240 | 04/07/2019 | 520i  | 93822   |

Tanjiu 97495749 / 62563561  
WP 13/11/24 @ 1230pm  
tanjiu e (khandu.com)  
03 days  
P/P Resurvey before paint.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



|                    |   |                 |
|--------------------|---|-----------------|
| Labour 1           | : | 2,640.00        |
| Parts              | : | 5,166.05        |
| Labour 2           | : | 0.00            |
| Excess             | : | 0.00            |
| Total GST @ 9%     | : | 702.54          |
| <b>Grand Total</b> | : | <b>8,508.59</b> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*