



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBL 5460K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HANDLE BAR	TO REPAIR SEE LABOUR	\$380.00	\$0.00
1	FRONT BALANCER RH	SERVICEABLE	\$285.00	\$0.00
1	FUEL TANK ASSY	TO REPAIR SEE LABOUR	\$650.00	\$0.00
1	FRONT BRAKE DISC	SERVICEABLE	\$385.00	\$0.00
1	FRONT BRAKE	SERVICEABLE	\$280.00	\$0.00
1	FRONT FORK	SERVICEABLE	\$1,120.00	\$0.00
1	FRONT BRAKE LEVER	TO REPAIR SEE LABOUR	\$298.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$339.80)	\$0.00
			<b>\$3,058.20</b>	<b>\$0.00</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LOWER IRON SUPPORT (SN)	BENT	\$500.00	\$320.00
			<b>\$500.00</b>	<b>\$320.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT HANDLE BAR, FUEL TANK ASSY AND FRONT BRAKE LEVER		\$500.00	\$50.00
	ANTI RUST	NOT NECESSARY	\$120.00	\$0.00
	CHECK WIRING SYSTEM	NOT NECESSARY	\$120.00	\$0.00
	TO DO SPRAY PAINTING ON ACCIDENT AREA	NOT NECESSARY	\$300.00	\$0.00
			<b>\$1,040.00</b>	<b>\$50.00</b>

<b>GRAND TOTAL</b>	<b>\$4,598.20</b>	<b>\$370.00</b>
--------------------	-------------------	-----------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>		<b>\$300.00</b>
---	--	-----------------

Report Ref No: CS/FCI24110162/Kvp3e2

MARKET VALUE: \$3,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,446.00=NETT VALUE: \$1,554.00

**KSC**

KENNETH KONG SENG CHEONG



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.