


PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0845/2024/KS 29-Nov-24 GLORY 1 of 1 SBK 888 Z AUDI E-TRON 50 QUATTRO GE
Quantity	Description	Unit Price	Amount
Labours			
1	TO DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$ 480.00 /	
2	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. TO CHECK ON ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,800.00 /	
3	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	
4	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. 600 x 3	\$ 1,800.00 /	
Parts			
1	BONNET / DD	\$ 5,890.00	
2	FRONT LOCK CARRIER / BR	\$ 1,443.00	
3	FRONT FENDER UPPER BRACKET RHS / BT	\$ 105.00	
4	FRONT FENDER UPPER BRACKET LHS / BT	\$ 111.00	
5	READY MIX-COOLANT 1L / Nec	10 \$ 553.00	
6	STICKER FOR AIRCON / Nec	\$ 23.00	
GRAND TOTAL		\$ 13,405.00	


For Premium Automobiles Pte Ltd

Add 3 days (Replaced front support)

 Authorised Signature

Steve (LKK)
 06/12/24

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6386 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBK 888 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE. <i>470 x 1</i>	S/N \$ 900.00 <i>450 + 450 = 900</i> ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>60 x 1</i>	\$ 3,600.00 <i>1200</i>	
4	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS. <i>650 x 2</i>	\$ 4,400.00 <i>1300</i>	
5	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS.	S/N \$ 800.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00 ✓	
TOTAL LABOUR CHARGES		\$ 10,472.00	

+ 3 days

Car 2/12 WIP 37597

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1163

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

After Steve

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBK 888 Z


DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER X R	1	\$ 3,254.00	
2	FRONT BUMPER FIXING PARTS ✓	1	\$ 696.00	
3	FRONT BUMPER CLOSING ELEMENTS - CENTER X / BR	1	\$ Front grille backing 279.00	
4	FRONT BUMPER FOAM - LH INNER ?	1	\$ 38.00	
5	FRONT BUMPER LOWER GRILLE COVER - LH / RH X	2	\$ 88.00	
6	FRONT BUMPER FOAM - SQUARE ?	1	\$ 169.00	
7	FRONT BUMPER FOAM - LONG ?	1	\$ 141.00	
8	FRONT PLASTIC FOAM STRIP - LOWER COVER X	1	\$ 151.00	
9	FRONT BUMPER GRILLE - LOWER CENTRE X	1	\$ 318.00	
10	FRONT BUMPER GRILLE - CENTER X	1	\$ 192.00	
11	FRONT BUMPER CLOSING ELEMENT - LOWER X	1	\$ 263.00	
12	FRONT BUMPER AIR GUIDE - LH / RH X	2	\$ 228.00	
13	FRONT BUMPER IMPACT PROTECTION - LOWER X	1	\$ 1,011.00	
14	FRONT BUMPER SPOILER - LH / RH X	2	\$ 248.00	
15	FRONT BUMPER AIR GUIDE - LH / RH INNER X	2	\$ 136.00	
16	FRONT BUMPER AIR GUIDE - LH / RH OUTER X	2	\$ 106.00	
17	FRONT BUMPER TRIM - LH / RH X	2	\$ 146.00	
18	FRONT BUMPER AIR GUIDE - LH / RH BRILLIANT BLACK X	2	\$ 300.00	
19	RADIATOR GRILLE X CUT	1	\$ 2,582.00	
20	RADIATOR GRILLE AUDI EMBLEM COVER X	1	\$ 83.00	
SUB TOTAL SPARE PARTS		:	\$ 10,429.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408690
 TEL : 6366 2323 FAX : 6541 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBK 888 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE STRIKER PLATE  <i>RR</i>	1	\$	275.00
22	RADIATOR GRILLE COVER - LH / RH 	2	\$	136.00
23	FRONT "360" DEGREE CAMERA 	1	\$	1,253.00
24	FRONT "360" DEGREE CAMERA COVER CAP 	1	\$	158.00
25	FRONT "360" DEGREE CAMERA BRACKET 	1	\$	116.00
26	FRONT "360" DEGREE CAMERA SECURING PLATE 	1	\$	104.00
27	FRONT BUMPER TOP COVER  <i>RR</i>	1	\$	134.00
28	NOTICE  <i>ML (Hkly)</i>	1	\$	25.00
29	FRONT BUMPER TOP COVER  / BR	1	\$	133.00
30	FRONT BUMPER TOP BRACKET  <i>RR</i>	1	\$	540.00
31	FRONT REINFORCEMENT BEAM 	1	\$	1,663.00
32	FRONT CROSS MEMBER 	1	\$	521.00
33	FRONT BUMPER SUPPORT - LH / RH 	2	\$	144.00
34	LED HEADLIGHT, MATRIX BEAM - LH / RH  <i>ruj - LH - 2 \$ RH - BR</i>	2	\$	19,674.00
35	LIFT CYLINDER - LH / RH 	2	\$	566.00
36	LIFT CYLINDER HOSE 	1	\$	122.00
37	BONNET  <i>RR</i> x nn - refer supp quote wrong price		\$	233.00
38	BONNET HINGE - LH / RH 	2	\$	420.00
39	BONNET IMPACT PROTECTION - LH / RH  <i>ML</i>	2	\$	112.00
40	BONNET IMPACT PROTECTION - CENTER  <i>RR</i>	1	\$	38.00
SUB TOTAL SPARE PARTS		:	\$	26,367.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6941 1163
EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBK 888 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	PLENUM CHAMBER COVER ✓	1	\$	249.00
42	BONNET STRIKER - LH / RH ✓	2	\$	298.00
43	BONNET RELEASE ELEMENT ✓	1	\$	73.00
44	BONNET LOCK (LH / RH) - *-- / BT	2	\$	491.00
45	BONNET BOWDEN CABLE - CENTER ✓	1	\$	71.00
46	BONNET BOWDEN CABLE - CABLE ✓	1	\$	12.00
47	BONNET CABLE ✓	1	\$	92.00
48	FRONTAL TOP COVER - LH / RH ✓	2	\$	254.00
49	FRONTAL TOP COVER - LH / RH ✓	2	\$	124.00
50	RADIATOR AIR GUIDE - LH / RH ?	2	\$	84.00
51	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$	53.00
52	RADIATOR LOUVRE - LOWER ?	1	\$	272.00
53	RADIATOR LOUVRE SERVOMOTOR ?	1	\$	209.00
54	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$	188.00
55	FRONT WHEEL ARCH COVER - LH / RH ✓ NK	2	\$	728.00
56	FRONT NO PLATE ✓ NK	S/N	\$	60.00
57	SUNDRIES ?		\$	500.00
TOTAL SPARE PARTS			:	\$ 3,758.00
TOTAL LABOUR CHARGES			:	\$ 4,972.00
GRAND TOTAL			:	\$ 8,730.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Steve (LKK)
06/12/24
Resurvey