

Performance Motors

BMW Dealer



Supplementary

Estimate No. : **b1 71805**
Date Estimated : **14/11/2024**
Prepared By : **Jack Ng Guo Ming**

Page No. :

- ESTIMATE REPAIR FOR -

Seow Khim Chuang (Xiao Jinchuan)
Blk 10 Pari Dedap Walk
#09-21

Singapore 486062

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMU7690Y	WBA5F32070FH84693	28/08/2020	320i Sedan	52567

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH BUMPER TOP GUIDE	20.55	1.00	0.00	20.55
# RH SUPPORT (NSW)	123.85	1.00	0.00	123.85
# RH TRIM GRILLE WITH PDC (M/PDC)	91.30	1.00	0.00	91.30

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	235.70
Total Labour & Parts (before GST) :	235.70
Deduction for Excess :	
Total Repair Costs less Excess:	235.70
GST @9%:	21.21
Grand Total :	256.91

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

