

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLQ531C

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES2400948/YISHUN
Date: 14 Nov 2024
Policy No: 5091922454-07
Veh Reg No: SLQ531C
Make/Model: TOYOTA TOYOTA
COROLLA AXIO 1.5G
CVT

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 08/11/2024
TP Veh Reg No: GBK4873P

Not Notified
1/1 Sup & 4/150h
Resurvey After Repair
5 days

Chassis No: NRE1610023604
Engine No: 2NR8701194
Reg. Date: 27/06/2017

Estimate Repair Cost to Vehicle No :SLQ531C

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	774.30	1 PC	774.30	✓
2 REAR BUMPER LH SIDE RETAINER	153.50	1 PC	153.50	✓
3 REAR BUMPER LH BRACKET	92.10	1 PC	92.10	✓
4 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
5 TAILLAMP LH	876.60	1 PC	876.60	✓
6 TAILLAMP LOWER BRACKET LH	99.80	1 PC	99.80	✓
7 REAR BOOT	1,299.10	1 PC	1,299.10	✓
8 REAR BOOT LOGO	68.80	1 PC	68.80	✓
9 REAR BOOT EMBLEM (AXIO)	63.20	1 PC	63.20	✓
10 REAR BOOT INNER LOCK	183.40	1 PC	183.40	x
11 REAR BOOT INNER RUBBER	269.40	1 PC	269.40	✓
12 REAR BOOT EMBLEM (G)	59.10	1 PC	59.10	✓
13 REAR BOOT OUTER MOULDING	301.30	1 PC	301.30	✓
14 REAR PANEL	902.30	1 PC	902.30	✓
15 REAR PANEL INNER TOP GARNISH	374.50	1 PC	374.50	✓
			5,540.80	
		Less 25%	1,385.20	4,155.60
Special Net				
16 REVERSE SENSOR	200.00	1 SET	200.00	✓
			200.00	200.00
Labour				
17 REMOVE & REFIX REAR BUMPER ASSY,BOOT & ATTACHMENT,TO CUT,WELD & RENEW REAR PANEL,KNOCK & REPAIR REAR LH FENDER AND REALIGN THE SAME	800.00	1 LA	800.00	600
18 PUTTY & RESPRAY ON REAR BUMPER,BOOT,REAR LH FENDER,REAR PANEL AND REAR AFFECTED AREAS	800.00	1 LA	800.00	700
19 RUSTPROOFING	30.00	1 LA	30.00	✓
20 REMOVE & REFIX REAR REVERSE CAMERA,REAR REVERSE SENSOR	30.00	1 LA	30.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1,660.00 1,660.00
Total S\$ 6,015.60
Add GST @ 9% 541.40
Total Amount Payable S\$ 6,557.00

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE