

(08/11/13) Wet

ASS. REC. BY:

REF:

CO/LPC24110184/Xua3

281F

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SNH 5488K

at Workshop m/s VANMAG

of ALEXANDRA RD

Insured: LPC

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

10-30

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

126K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 40K

Veh No:

SNH 5488K

Yr Regn: 2022 / 56P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B40 ATD 3

C.C.

Colour:

RED

AC: Insured / Std / NI / NA

Sp. Reading:

77004

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LHXC4CBSN2081384

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R18

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ATLAS

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/11/24

D.O.I.

29/11/24

Survey held at

ALEXANDRA

Des. of Damages: Frt (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Prel. Report

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format:

Lump Sum / I.B.I.: (\$

TOTAL

305 Alexandra Road
159942 Singapore

Tel : 6376 8833
Fax : 6477 7398

GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. BY 7066	Date Estimated 23/11/2024	Page No. 1 of 2
	Prepared By Muhammad Danial Bin Ishak	

ESTIMATE REPAIR FOR Lee Ban Chin 1 Elias Green #13-06 Singapore 519959	ACCOUNT 14805 Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNH5488K	LGXCE4CB5N2081384	21/09/2022	Atto 3	74921

DESCRIPTION	VALUE
TO CONDUCT THIRD PARTY CLAIM AGAINST LONPAC INS. (SLH4423M)DOA.08.11.24	0.00
TO REMOVE & REPLACE REAR BUMPER, REAR TAILGATE, REAR END PANEL.	1200 1,850.00
TO REPAIR/PANEL BEAT FLOR PANEL.	? 650 850.00
TO REMOVE & REPLACE REAR WINDSCREEN AND CONDUCT WATER LEAK TEST.	600.00
TO SUPPLY & INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN.	350.00
TO SUPPLY & INSTALL REAR PLATE NUMBER WITH FRAME.	70.00
TO REMOVE & REPLACE REAR BUMPER WIRE, PARKING SENSORS AND ALL ELECTRICAL PARTS .	300? 600.00
TO SPRAY PAINT REAR BUMPER, REAR TAILGATE, REAR END PANEL, REAR FLOOR PANEL.	1200 2,480.00
TO CONDUCT BODY CAVITY PRESERVATIONS.	30 128.00
TO CONDCUT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION .	600.00
SUNDRIES.	20 108.00
Total Labour 1:	7,590.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
13161637-00	TRIM COVER INNER LH - REAR BUMPER	1	24.49	0.00	24.49
13161636-00	TRIM COVER INNER RH - REAR BUMPER	1	24.49	0.00	24.49
13161517-00	TRIM OF REAR BUMPER	1	54.63	0.00	54.63
13220424-00	TRIM - LOWER SURROUND REAR BUMPER	1	47.97	0.00	47.97
13814520-00	BUMPER BODY ASSY.,REAR	1	546.00	0.00	546.00
13678676-00	RR LICENSE PLATE BASE ASSY	1	11.21	0.00	11.21
13182878-00	REAR PEDAL ASSY	1	39.30	0.00	39.30
13220230-00	RR LICENSE PLATE TRIM PANEL ASSY	1	24.49	0.00	24.49
13688366-00	ATTO WORD MARK ASSY	1	6.68	0.00	6.68
13276895-00	BUILDYOURDREAM WORD MARK ASSY	1	13.57	0.00	13.57
13777456-00	BACK DOOR ASSEMBLY	1	978.93	0.00	978.93
13778440-00	REAR FLOOR PANEL ASSY	1	597.15	0.00	597.15
13778327-00	REAR PANEL ASSEMBLY	1	332.86	0.00	332.86
13777448-00	IMPACT BEAM.,REAR	1	111.48	0.00	111.48

uto

ision of Vantage Automotive Limited)

ess Registration No. 53399829L GST Registration No. M2-0000551-1

395 Alexandra Road

159942 Singapore

Tel : 6376 8833

Fax : 6477 7396

343

GST Registration No. M2-0000551-1

ESTIMATE



Date Estimated

Page No. 2 of 2

Estimate No.

23/11/2024

BY 7066

Prepared By

Muhammad Danial Bin Ishak

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SNH5488K

LGXCE4CB5N2081384

21/09/2022

Atto 3

74921

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
13171273-00	WINDSCREEN ASSY - REAR <i>am / pluh</i>	1	125.14	0.00	125.14
13401407-00	REAR BUMPER WIRE ?	1	67.21	0.00	67.21
13195410-00	SMALL PROBE (PIANO BLACK) ?	2	11.12	0.00	22.24
13596478-00	PANORAMIC & REAR VIEW IMAGE MODULE ?	1	115.52	0.00	115.52
13243525-00	LEFT COMB TAIL LAMP BAFFLE X	1	5.17	0.00	5.17
13184244-00	MIDDLE TAIL LAMP X	1	558.00	0.00	558.00
13184245-00	RIGHT COMB TAIL LAMP ASSY X	1	254.52	0.00	254.52
11721028-00	FOG LAMP, REAR ?	1	44.55	0.00	44.55

Total Parts : 4,005.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame
Hp 9000068
4 days
29/11/24
Res by paint

Labour 1	S\$	7,590.00
Parts	S\$	4,005.60
Labour 2	S\$	0.00
Excess	S\$	0.00
Total GST @ 9%	S\$	1,043.60
Grand Total	S\$	12,639.20

Customer Name & Signature / Company Stamp

Date

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	281F
Vehicle Details	
Vehicle No.:	SNH5488K
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Dec 2024
Vehicle Make:	BYD
Vehicle Model:	ATTO 3
Primary Colour:	Red
Manufacturing Year:	2022
Engine No.:	-
Chassis No.:	LGXCE4CB5N2081384
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$34,000.00
Original Registration Date:	21 Sep 2022
First Registration Date:	21 Sep 2022
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2032
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2032
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$114,001.00
COE Rebate Amount:	\$85,832.00
Total Rebate Amount:	\$85,832.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Dec 2024

OK

BYD Atto 3 Electric Sunroof

\$143,800 Instalment \$1,205/mth

PREMIUM AD

 Shortlist  Loan Calculator

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!



VIEW ALL PROMO

Overview Financial Photo Research

Depreciation	 \$16,150 / year
Reg. Date	25-Oct-2023 (8yrs 10mths 23days COE left)
Manufactured	 2023
Mileage	16,000 km (14.5k / year)
Transmission	Auto
Road Tax	 \$1,502 / year
Power	100.0 kW (134 bhp) View specs of the BYD Atto 3 Electric (2022)
Curb Weight	 1,750 kg
Fuel Type	Electric
Drive Range	-
COE	 \$101,000
OMV	 \$34,000
Dereg Value	 \$80,800 as of today
No. of Owners	 1